



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 DRIVE SE START/STOP
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C








Internet history

Entry 1

Date	2021-09-27
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-16
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #11

2023-08-17 13:29

MOT test number

823917952882

Result

✓ Passed

Next expiry date

2024-08-16

Advice

Undertray fitted

MOT #10

2022-07-15 12:57

MOT test number

349456802524

Result

✓ Passed

MOT #9

2021-10-18 12:09

MOT test number

818764194783

Result

✓ Passed

MOT #8

2021-10-04 14:28

MOT test number

959982555393

Result

✗ Failed

Fail

Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #7** 2020-09-24 15:52**MOT test number** 425977408796**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))**MOT #6** 2019-09-25 14:06**MOT test number** 308979656711**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-09-27 12:41**MOT test number** 612798753947**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge n/s & o/s & worn on inner edge (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #4** 2018-09-27 12:40**MOT test number** 246509363426**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge n/s & o/s & worn on inner edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #3** 2017-09-07 11:08**MOT test number** 801736999635**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit & worn on inner edge (4.1.E.1)**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #2** 2017-09-07 11:08**MOT test number** 586043820242**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit & worn on inner edge (4.1.E.1)**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #1** 2016-07-18 15:48**MOT test number** 431442352413**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YE12XKP
Plate since	2019-09-29
Current registration	YE12XKP
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-13
Last registration	2023-08-17
Complete history	See info



Registration #1	2012-06-13	18 mi
Registration #2	2016-07-18	75.933 mi
Registration #3	2017-09-07	86.730 mi
Registration #4	2017-09-07	86.730 mi
Registration #5	2018-09-27	98.460 mi
Registration #6	2018-09-27	98.460 mi
Registration #7	2019-09-25	110.178 mi
Registration #8	2019-09-25	110.178 mi
Registration #9	2019-09-25	110.178 mi
Registration #10	2019-09-25	110.178 mi
Registration #11	2019-09-25	110.178 mi
Registration #12	2019-09-25	110.178 mi
Registration #13	2019-09-25	110.178 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1582 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4130882