



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T230 TREND HR P/V
Colour	Blue
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-05-10
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	43
Total items failed	15

MOT #13 2020-05-11 09:27

MOT test number 748194449848

Result ✓ Passed

Next expiry date 2021-05-10

Advice Windscreen cracked outside zone a

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #12 2020-05-04 13:30

MOT test number 279266364915

Result ✗ Failed

MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Windscreen cracked outside zone a

MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced inner floor to sill (7.1.1 (a) (i))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill full length (7.1.1 (a) (i))



MOT #112019-03-16 11:13

MOT test number300044657005

Result

✓ Passed

- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Oil leak, but not excessive Transmission (8.4.1 (a) (i))
- Advice

Both front tyres worn on inner edges.
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced Nearside outer sill (6.1.1 (c) (i))

**MOT #10**

2019-03-13 11:29

MOT test number

785577882243

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Brake pipe excessively corroded Nearside rear to front (1.1.11 (c))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Nearside outer sill (6.1.1 (c) (i))
- MAJOR** Offside Obligatory mirror insecure (3.3 (b) (ii))
- MAJOR** Fuel tank leaking (6.1.3 (b) (i))
- MAJOR** Rear Lower Engine mounting damaged or deteriorated resulting in excessive movement Stabiliser link (6.1.8 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Both front tyres worn on inner edges.
- MAJOR** Central Stop lamp(s) showing white light to the rear (4.3.3 (a) (ii))

**MOT #9**

2018-01-24 13:54

MOT test number

772030145122

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)
- Advice** Clutch anti slip pedal rubber damaged
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' Scratch across screen, Not in drivers view of the road at time of test (8.3.1a)
- Advice** Oil leak

MOT #8

2018-01-24 12:08

MOT test number

428288365556

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' Scratch across screen, Not in drivers view of the road at time of test (8.3.1a)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Oil leak
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Clutch anti slip pedal rubber damaged
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Rear Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)



MOT #7	2016-11-21 15:00
MOT test number	198798662442
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #6	2016-11-16 12:19
MOT test number	445208218297
Result	✗ Failed
Fail	Nearside Stop lamp not working when side lights are on, I suspect the bulb is fitted wrong (1.2.1b)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Stop lamp not working (1.2.1b)
Fail	Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #5	2015-11-12 10:17
MOT test number	429442090161
Result	✓ Passed

**MOT #4** 2015-11-10 14:00**MOT test number** 696048167564**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Inner sidewall has age cracks / splits**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2014-08-27 15:28**MOT test number** 457969134217**Result** ✓ Passed**MOT #2** 2014-08-22 08:59**MOT test number** 268774034214**Result** ✗ Failed**Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)**MOT #1** 2013-10-14 09:35**MOT test number** 209307983263**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2021

✕
MOT

Expired:
10 May 2021

Tax status	Expired at 1 February 2021
Days left	1182 days too late
MOT expiry date	10 May 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-06
Last registration	2020-05-11
Complete history	See info



Registration #1	2010-12-06	13 mi
Registration #2	2013-10-14	60.433 mi
Registration #3	2014-08-22	745.921 mi
Registration #4	2014-08-27	74.593 mi
Registration #5	2015-11-10	89.327 mi
Registration #6	2015-11-12	89.329 mi
Registration #7	2016-11-16	100.837 mi
Registration #8	2019-05-20	101.277 mi
Registration #9	2019-05-20	101.277 mi
Registration #10	2019-05-20	101.277 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Kerb weight	1438 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	AR47042