



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Blue
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-07-15
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-19
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	54
Total items failed	10

MOT #23	2023-11-20 16:16
MOT test number	250202274396
Result	✓ Passed
Next expiry date	2024-11-19
Advice	Nearside Play in steering rack inner joint(s)
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #22**

2023-11-16 13:21

MOT test number

458422750351

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Nearside Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** EML On
- MAJOR** Rear Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- DANGEROUS** Offside Rear Valve stem seriously damaged (5.2.3 (j))
- MAJOR** Nearside Rear Body component damaged and likely to cause injury lamp holed (6.2.1 (a) (i))

MOT #21

2022-09-06 14:28

MOT test number

926156760169

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2022-08-16 09:23

MOT test number

723199289015

Result**✗ Failed**

- Advice** Offside Front Play in steering rack inner joint(s)
- MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** CLUTCH PEDAL RUBBER MISSING
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #19

2021-07-22 10:47

MOT test number

471571344480

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing Both sides slight (5.3.2 (b))



MOT #18	2021-07-22 10:47
MOT test number	685581805226
Result	✗ Failed
Advice	Rear Shock absorbers has slight external damage to the casing Both sides slight (5.3.2 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #17	2020-07-20 14:56
MOT test number	423207472249
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2019-08-06 15:48
MOT test number	129896187142
Result	✓ Passed

MOT #15	2018-07-26 11:44
MOT test number	870469200071
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
Advice	Clutch pedal rubber missing
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2018-07-26 11:44

MOT test number

177373896715

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Clutch pedal rubber missing**MOT #13**

2017-08-15 09:01

MOT test number

314802729059

Result**✓ Passed****Advice** Nearside Rear rubber dust cover of rear suspension strut splitting**Advice** Offside front and offside rear tyres have slight cracking on outer sidewalls of tyres**MOT #12**

2017-08-15 09:01

MOT test number

993844127274

Result**✗ Failed****Advice** Nearside Rear rubber dust cover of rear suspension strut splitting**Pass with rectification** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside front and offside rear tyres have slight cracking on outer sidewalls of tyres**Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #11** 2016-08-16 15:49**MOT test number** 658710314737**Result** ✓ Passed**MOT #10** 2016-08-15 10:45**MOT test number** 770217202059**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2015-11-24 13:03**MOT test number** 593147961793**Result** ✓ Passed**MOT #8** 2015-04-24 16:41**MOT test number** 875594715144**Result** ✓ Passed**MOT #7** 2015-04-23 12:44**MOT test number** 268633815422**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2014-04-24 14:47**MOT test number** 445524714174**Result** ✓ Passed**Notice** Exhaust tailpipe support strap rusted



MOT #5	2013-04-22 13:54
MOT test number	225662113178
Result	✓ Passed
MOT #4	2012-05-01 11:26
MOT test number	648232822195
Result	✓ Passed
MOT #3	2012-05-01 11:26
MOT test number	175312022188
Result	✗ Failed
<div>Pass with rectification</div> Nearside Registration plate lamp not working (1.1.C.1d)	
MOT #2	2011-04-27 13:17
MOT test number	435767811103
Result	✓ Passed
MOT #1	2010-05-10 13:29
MOT test number	951330930124
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
19 November 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	EJ07UON
Plate since	2019-09-28
Current registration	EJ07UON
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-05-18
Last registration	2023-11-20
Complete history	See info



Registration #1	2007-05-18	18 mi
Registration #2	2010-05-10	17.043 mi
Registration #3	2011-04-27	23.354 mi
Registration #4	2012-05-01	29.532 mi
Registration #5	2013-04-22	36.727 mi
Registration #6	2014-04-24	44.323 mi
Registration #7	2015-04-23	51.983 mi
Registration #8	2015-04-24	52.014 mi
Registration #9	2015-11-24	56.665 mi
Registration #10	2016-08-15	64.447 mi
Registration #11	2016-08-16	64.450 mi
Registration #12	2017-08-15	73.843 mi
Registration #13	2018-05-20	81.277 mi
Registration #14	2019-05-20	89.277 mi
Registration #15	2020-05-20	97.277 mi
Registration #16	2021-05-20	105.277 mi
Registration #17	2022-05-20	113.277 mi
Registration #18	2023-05-20	121.277 mi
Registration #19	2023-05-20	121.277 mi
Registration #20	2023-05-20	121.277 mi
Registration #21	2023-05-20	121.277 mi
Registration #22	2023-05-20	121.277 mi
Registration #23	2023-05-20	121.277 mi
Registration #24	2023-05-20	121.277 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901