



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI
Colour	White
Year of manufacture	2013
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-19
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	20
Total items failed	0

MOT #12	2023-10-27 06:48
MOT test number	916963792558
Result	✓ Passed
Next expiry date	2024-10-26

MOT #11	2023-02-03 10:52
MOT test number	727340786095
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10	2022-02-04 13:07
MOT test number	252699547641
Result	✓ Passed

MOT #9	2021-01-11 09:15
MOT test number	949327473389
Result	✓ Passed

**MOT #8** 2021-01-11 08:25**MOT test number** 645271614493**Result** ✗ Failed**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #7** 2020-01-15 16:39**MOT test number** 962497635526**Result** ✓ Passed**MOT #6** 2019-09-03 11:57**MOT test number** 106908724159**Result** ✓ Passed**MOT #5** 2019-09-03 10:20**MOT test number** 211604646985**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-08-24 10:16**MOT test number** 126522090265**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

**MOT #3** 2018-08-21 11:11**MOT test number** 102244115192**Result** ✗ Failed**MAJOR** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))**MOT #2** 2017-09-01 12:53**MOT test number** 551915959388**Result** ✓ Passed**Advice** Rear both rear tyres cracked,nsr balding inner edge**MOT #1** 2016-09-13 11:20**MOT test number** 621250207537**Result** ✓ Passed**Advice** Nearside Front wiper torn but not smearing**Advice** Offside Rear tyre deep cut not reaching cords**Advice** Offside Front tyre bald edges and cracked badly not exposing cords**Advice** Both rear tyres cracked treads



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-10-31
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2013-10-31	21 mi
Registration #2	2016-09-13	17.195 mi
Registration #3	2017-09-01	25.933 mi
Registration #4	2018-08-21	36.216 mi
Registration #5	2018-08-24	36.218 mi
Registration #6	2019-09-03	44.260 mi
Registration #7	2019-09-03	44.260 mi
Registration #8	2019-09-03	44.260 mi
Registration #9	2019-09-03	44.260 mi
Registration #10	2019-09-03	44.260 mi
Registration #11	2019-09-03	44.260 mi
Registration #12	2019-09-03	44.260 mi
Registration #13	2019-09-03	44.260 mi
Registration #14	2019-09-03	44.260 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	G4FDDU454915