





report date: 2024-03-28

General information

Make	MINI
Model	ROADSTER COOPER S
Colour	Grey
Year of manufacture	2015
Top speed	141 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP	
Max. torque	240 Nm at 1.600 rpm	
Engine capacity	1.598 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	37.7 mpg	
Consumption extra urban	55.4 mpg	
Consumption combined	47.1 mpg	
CO2 emission	139 g/km	
CO2 label	E	



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-06-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-05-15
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #9	2024-04-25 09:01	
MOT test number 2790808523		
Result	✓ Passed	
Next expiry date 2025-05-15		
Minor Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking badly (5.2.3 (d) (ii))		

MOT #8	2023-05-12 11:18
MOT test number	638752496518
Result	✓ Passed
Advice Offside Rear tyre starting to perish	
Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functionin	g (4.3.1 (a) (i))

MOT #7	2023-05-12 10:13	
MOT test number	567801846759	
Result	× Failed	
Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))		
Fail Nearside Rear Road wheel fixing missing bolt (5.2.1 (a) (i))		
Advice Offside Rear tyre starting to perish		

CarCheck.co.uk page 3/11



MOT #6 2022-05-16 16:13

MOT test number 860647756805

MOT #5 2022-04-28 16:56

MOT test number 133964931991

Result X Failed

Fail Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Brake pad(s) wearing thin All around (1.1.13 (a) (ii))

MOT #4 2021-12-22 14:15

MOT test number 716702727393

Result ✓ Passed

MOT #3 2020-12-11 09:49

MOT test number 101407901797

Result ✓ Passed

MOT #2 2019-06-21 11:34

MOT test number 376804300809

Result ✓ Passed

MOT #1 2018-07-07 09:17

MOT test number 160450131193

Result ✓ Passed

Advice Nearside Front Tyre wearing on outer edge

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



GV15UFD

report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-29
Last registration	2024-04-25
Complete history	See info



Registration #1	2015-06-29	10 mi
Registration #2	2018-07-07	8.644 mi
Registration #3	2019-06-21	11.402 mi
Registration #4	2020-12-11	17.193 mi
Registration #5	2021-12-22	20.516 mi
Registration #6	2022-04-28	21.846 mi
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 au

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	2 p	age 11/11

Number of axles 2

Engine number A259J839