



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 3

Date	2023-07-13
Pictures	24
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2023-07-12
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-07-16
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-03-30
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	34
Total items failed	13

MOT #14	2024-03-16 13:17
MOT test number	333950193523
Result	✓ Passed
Next expiry date	2025-03-30
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #13	2023-03-29 10:25
MOT test number	135391726513
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12** 2022-03-16 11:12**MOT test number** 692035765399**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2021-03-22 15:59**MOT test number** 255962444717**Result** ✓ Passed**MOT #10** 2021-03-22 14:32**MOT test number** 228318116673**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2020-03-20 16:03**MOT test number** 575776344396**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2020-03-20 16:03

MOT test number

715143190638

Result**✗ Failed****Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7**

2019-03-31 14:14

MOT test number

735766331962

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6**

2018-03-20 09:30

MOT test number

828120989906

Result**✓ Passed****MOT #5**

2018-03-19 11:47

MOT test number

933576330014

Result**✗ Failed****Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Upper Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Central Front Tyre tread depth below requirements of 1.6mm BOTH AT 1MM (4.1.E.1)

**MOT #4** 2017-03-24 11:57**MOT test number** 749015367862**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #3** 2017-03-24 11:24**MOT test number** 385763583938**Result** ✗ Failed**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #2** 2015-09-01 15:52**MOT test number** 831047041866**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Wearing on edges (4.1.E.1)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit Wearing on edges (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #12015-09-01 15:05

MOT test number606993472161

Result

Failed

Fail

Front registration plate deteriorated (6.3.1d)

Advice

Offside Front Tyre worn close to the legal limit Wearing on edges (4.1.E.1)

Advice

Offside Front Seat belt stitching slightly frayed (5.2.2b)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice

Nearside Front Tyre worn close to the legal limit Wearing on edges (4.1.E.1)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 RF62RVT
Plate since	2019-06-29
Current registration	 RF62RVT
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-09-08
Last registration	2024-03-16
Complete history	See info



Registration #1	2012-09-08	7 mi
Registration #2	2015-09-01	30.261 mi
Registration #3	2015-09-01	30.261 mi
Registration #4	2017-03-24	47.385 mi
Registration #5	2017-03-24	47.385 mi
Registration #6	2018-03-19	56.077 mi
Registration #7	2018-03-20	56.117 mi
Registration #8	2019-03-31	66.898 mi
Registration #9	2020-03-20	75.431 mi
Registration #10	2020-03-20	75.431 mi
Registration #11	2020-03-20	75.431 mi
Registration #12	2020-03-20	75.431 mi
Registration #13	2020-03-20	75.431 mi
Registration #14	2020-03-20	75.431 mi
Registration #15	2020-03-20	75.431 mi
Registration #16	2020-03-20	75.431 mi
Registration #17	2020-03-20	75.431 mi
Registration #18	2020-03-20	75.431 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172361K