





report date: 2024-03-29

### General information

Make	LAND ROVER
Model	RANGE ROVER SDV6 VOGUE
Colour	Grey
Year of manufacture	2018
Top speed	130 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	271 BHP
Max. torque	625 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption combined	31.4 mpg
CO2 emission	199 g/km
CO2 label	J



CarCheck.co.uk page 1/11



## Internet history

Entry	1
Ellti y	-

Lifety 1	
Date	2021-12-22
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-12-17
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	4
Total items failed	8

MOT #5	2023-12-18 14:31
MOT test number	310928193552
Result	<b>✓</b> Passed
Next expiry date	2024-12-17

MOT #4	2023-12-18 09:36
MOT test number	960921437805
Result	<b>×</b> Failed
Fail Front Windscreen washer not working (3.5 (a))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Fail</b> Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2022-12-07 15:35
MOT test number	639770771856
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



**Advice** 

Fail

AJ68RDZ report date: 2024-03-29

MOT test number

952631949880

Result

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #1

MOT test number

Result

Advice

Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

Minor

Offside Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	17 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	К
First licence fee (12 months)	£ 1.565,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.220,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category

Damage 2

**Type** 

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	la : a b a .a
UWNER	INISTATV
OWITCH	THISCOLV

e when moterly	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	
********	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-12-05
Last registration	2023-12-18
Complete history	See info



Registration #1	2018-12-05	9 mi
Registration #2	2021-12-17	31.960 mi
Registration #3		11.777 es
Registration #4	2022-12-07	46.307 mi
Registration #5		11.777 mi
Registration #6		11.777 es
Registration #7		11,777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



# Dimensions & weight

Width	2220 mm
Height	1869 mm
Length	5000 mm
Wheel base	2922 mm
Kerb weight	2583 kg
Max. allowed weight	2385 kg

## Additional information

Fuel tank capacity	86 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1264335306DT

CarCheck.co.uk page 11/11