



WNI3UWK

report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ3
Colour	Grey
Year of manufacture	-
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-09
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

**MOT #12** 2022-05-31 10:31**MOT test number** 555405283595**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11** 2021-06-16 12:29**MOT test number** 382198176832**Result** ✓ Passed**MOT #10** 2020-10-20 15:45**MOT test number** 192185151371**Result** ✓ Passed**MOT #9** 2020-10-20 15:32**MOT test number** 284453311793**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-10-21 08:59**MOT test number** 691379934836**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge o/s/f+ n/s/r (5.2.3 (e))

**MOT #7** 2019-10-18 14:24**MOT test number** 546806315448**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Tyre worn close to legal limit/worn on edge o/s/f+ n/s/r (5.2.3 (e))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2018-10-23 14:31**MOT test number** 926470288156**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2017-10-16 15:58**MOT test number** 911804640403**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine oil on minimum**Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2017-10-16 15:58**MOT test number** 351659192320**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine oil on minimum**Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-10-21 07:05**MOT test number** 972652650378**Result** ✓ Passed**MOT #2** 2016-10-20 14:25**MOT test number** 487774290820**Result** ✗ Failed**Advice** Nearside Rear wheel bearing slightly rough when rotated**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)**MOT #1** 2016-03-31 12:01**MOT test number** 316235157195**Result** ✓ Passed**Advice** Front wiper blades worn**Advice** Offside Rear tyre starting to perish**Advice** Nearside Front tyre perish/ crack in outer side wall



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>WN13UWK</b>
Plate since	2019-03-29
Current registration	<b>WN13UWK</b>
Plate since	2019-03-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-30
Last registration	2022-05-31
Complete history	<a href="#">See info</a>



Registration #1	2013-03-30	10 mi
Registration #2	2016-03-31	52.889 mi
Registration #3	2016-10-20	61.260 mi
Registration #4	2016-10-21	61.261 mi
Registration #5	2017-10-16	73.212 mi
Registration #6	2017-10-16	73.212 mi
Registration #7	2018-10-23	97.122 mi
Registration #8	2019-05-29	101.277 mi
Registration #9	2019-05-29	101.277 mi
Registration #10	2019-05-29	101.277 mi
Registration #11	2019-05-29	101.277 mi
Registration #12	2019-05-29	101.277 mi
Registration #13	2019-05-29	101.277 mi
Registration #14	2019-05-29	101.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1610074