



RENAULT

 **LMI4FPD**


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A





**Internet history**

**Entry 1**

Date	2021-06-29
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	30
Total items failed	1

MOT #12 2023-08-10 15:17

MOT test number 182418687892

Result ✔ Passed

Next expiry date 2024-08-11

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources offside rear (4.7.1 (b) (i))

**Advice** Nearside front head light bracket broken but sill secure

**Advice** Shock absorbers has light misting of oil offside front (5.3.2 (b))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

**Advice** Rear bumper offside slight damaged

**Advice** Registration plate deteriorated but not likely to be misread rear (0.1 (b))



MOT #11 2023-08-10 13:41

MOT test number 105156048172

Result ✗ Failed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- MAJOR** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt nearside front cv boot outer loose (6.1.7 (g) (ii))
- Advice** Nearside front head light bracket broken but sill secure
- Advice** Shock absorbers has light misting of oil offside front (5.3.2 (b))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources offside rear (4.7.1 (b) (i))
- Advice** Rear bumper offside slight damaged
- Advice** Registration plate deteriorated but not likely to be misread rear (0.1 (b))

MOT #10 2022-08-12 13:44

MOT test number 380882442540

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5mm , worn on edges (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front headlamp bracket broken but still secure



<b>MOT #9</b>	2022-08-12 08:14
<b>MOT test number</b>	411813888213
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>MAJOR</b>	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Advice</b>	Nearside Front headlamp bracket broken but still secure
<b>MAJOR</b>	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip broken (6.1.7 (g) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge 2.5mm , worn on edges (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>MAJOR</b>	Nearside Front Headlamp aim not tested (4.1.2 (b))

<b>MOT #8</b>	2021-08-03 15:25
<b>MOT test number</b>	918476757554
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #7</b>	2021-01-26 15:27
<b>MOT test number</b>	542286753871
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2020-02-03 16:11
<b>MOT test number</b>	185754084640
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2020-02-03 13:49
<b>MOT test number</b>	969201897779
<b>Result</b>	✗ Failed

<b>MAJOR</b>	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
--------------	---



<b>MOT #4</b>	2019-12-11 14:07
<b>MOT test number</b>	869243320582
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))
<b>MAJOR</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Offside Rear reflector damaged with sharp edges
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #3</b>	2018-12-04 16:13
<b>MOT test number</b>	708504596480
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2018-12-04 16:13
<b>MOT test number</b>	103848040730
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim too low (4.1.2 (a))

<b>MOT #1</b>	2017-05-18 08:04
<b>MOT test number</b>	843920689397
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
11 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	11 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable




Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2014-03-29
<b>Last registration</b>	2023-08-10
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2014-03-29	22 mi
<b>Registration #2</b>	2017-05-18	22.174 mi
<b>Registration #3</b>	2018-12-04	34.139 mi
<b>Registration #4</b>	2018-12-04	34.139 mi
<b>Registration #5</b>	2019-12-11	40.511 mi
<b>Registration #6</b>	2020-02-03	40.728 mi
<b>Registration #7</b>	2020-02-03	40.728 mi
<b>Registration #8</b>	2020-02-03	40.728 mi
<b>Registration #9</b>	2020-02-03	40.728 mi
<b>Registration #10</b>	2020-02-03	40.728 mi
<b>Registration #11</b>	2020-02-03	40.728 mi
<b>Registration #12</b>	2020-02-03	40.728 mi
<b>Registration #13</b>	2020-02-03	40.728 mi
<b>Registration #14</b>	2020-02-03	40.728 mi

[More info >](#)



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D292824