





report date: 2024-03-29

## General information

Make	FIAT
Model	500C LOUNGE
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP	
Max. torque	102 Nm at 3.000 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	51.4 mpg	
Consumption extra urban	65.7 mpg	
Consumption combined	60.1 mpg	
CO2 emission	110 g/km	
CO2 label	В	



CarCheck.co.uk page 1/12




## Internet history

## Entry 2

Date 2022-04-02

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk


Entry 1

Date	2022-02-20


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-11
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #9	2024-04-04 11:51
MOT test number	421131932181
Result	✓ Passed
Next expiry date	2025-04-11
Advice Front BOTH FRONT SHOCK TOP MOUNTS HAVE SLIGHT MOVEMENT	

MOT #8		2023-04-12 13:38
MOT test	number	952566253924
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii	))
Advice	Clamp missing rear exhaust	

CarCheck.co.uk page 3/12



MOT #7 2023-04-11 08:13

**MOT test number** 705883606342

Result X Failed

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Clamp missing rear exhaust

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2022-04-11 14:16

**MOT test number** 647069071237

**Result** 
✓ Passed

MOT #5 2021-10-15 14:07

**MOT test number** 963365624936

Result \( \sqrt{Passed} \)

MOT #4 2020-09-23 13:52

**MOT test number** 518273734505

Result 

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #3 2019-09-12 08:33

MOT test number 822631088044

Result 

Passed

CarCheck.co.uk page 4/12



MOT #2 2018-09-28 07:32 **MOT test number** 577335684523 ✓ Passed Result MOT #1 2018-09-27 09:24 **MOT test number** 273497633998 × Failed Result Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) **Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	11 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



NJ65HWA

report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-29
Last registration	2024-04-04
Complete history	See info



Registration #1	2015-09-29	19 mi
Registration #2	2018-09-27	23.694 mi
Registration #3	2018-09-28	23.695 mi
Registration #4	2019-09-12	31.064 mi
Registration #5	2020-09-23	37.374 mi
Registration #6	2021-10-15	42.478 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number1418138