



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 VIBE
Colour	Blue
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT #17	2023-03-07 17:01
MOT test number	791036977476
Result	✓ Passed
Next expiry date	2024-03-07

MOT #16	2023-03-07 17:01
MOT test number	129088465232
Result	✗ Failed

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

MOT #15	2022-03-03 14:36
MOT test number	571803577207
Result	✓ Passed

**Advice** Front discs corroded

MOT #14	2021-03-06 12:21
MOT test number	545222733300
Result	✓ Passed

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #13	2021-03-06 12:21
MOT test number	775845867799
Result	✗ Failed

**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**MOT #12**

2021-03-05 11:37

**MOT test number**

811458251953

**Result**

✗ Failed

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11**

2020-02-24 10:04

**MOT test number**

626636942808

**Result**

✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both fronts (5.3.4 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #10**

2019-03-01 12:11

**MOT test number**

362185012226

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front arm bushes deteriorated but functioning, both sides (5.3.4 (a) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #9** 2019-03-01 11:14**MOT test number** 588640585737**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front arm bushes deteriorated but functioning, both sides (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-03-08 09:53**MOT test number** 148965955615**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2017-02-27 12:05**MOT test number** 452106356334**Result** ✓ Passed



<b>MOT #6</b>	2016-02-08 12:52
---------------	------------------

<b>MOT test number</b>	892232813695
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2015-03-04 11:15
---------------	------------------

<b>MOT test number</b>	695043065060
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2014-02-15 09:49
---------------	------------------

<b>MOT test number</b>	878836644046
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-02-11 16:48
---------------	------------------

<b>MOT test number</b>	946172143061
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-02-08 10:28
---------------	------------------

<b>MOT test number</b>	439639332040
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2011-02-09 11:55
---------------	------------------

<b>MOT test number</b>	305480541080
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Rear wiper torn
---------------	-----------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-06
Last registration	2023-03-07
Complete history	<a href="#">See info</a>



Registration #1	2008-03-06	13 mi
Registration #2	2011-02-09	4.868 mi
Registration #3	2012-02-08	5.976 mi
Registration #4	2013-02-11	6.509 mi
Registration #5	2014-02-15	6.718 mi
Registration #6	2015-03-04	10.529 mi
Registration #7	2016-02-08	14.678 mi
Registration #8	2017-02-27	18.569 mi
Registration #9	2018-03-08	21.114 mi
Registration #10	2019-03-01	23.751 mi
Registration #11	2020-03-01	25.377 mi
Registration #12	2021-03-01	25.377 mi
Registration #13	2022-03-01	25.377 mi
Registration #14	2023-03-01	25.377 mi
Registration #15	2024-03-01	25.377 mi
Registration #16	2025-03-01	25.377 mi
Registration #17	2026-03-01	25.377 mi
Registration #18	2027-03-01	25.377 mi
Registration #19	2028-03-01	25.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5074259