





report date: 2024-03-28

General information

| Make | CITROEN |
|---------------------|----------------|
| Model | C1 FEEL |
| Colour | Red |
| Year of manufacture | 2016 |
| Top speed | 99 mph |
| 0 - 60 mph | 14.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 68 BHP |
|-------------------------|--------------------|
| Max. torque | 95 Nm at 4.800 rpm |
| Engine capacity | 998 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 68.9 mpg |
| CO2 emission | 95 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/12



Internet history

Entry 1

| Date | 2021-01-29 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-03-16 |
|--------------------|------------|
| MOT pass rate | 56 % |
| MOT passed | 5 |
| Failed MOT tests | 4 |
| Total advice items | 9 |
| Total items failed | 7 |

| MOT #9 | 2023-03-15 09:19 |
|------------------|------------------|
| MOT test number | 294793057440 |
| Result | ✓ Passed |
| Next expiry date | 2024-03-16 |

 MOT #8
 2023-03-14 11:02

 MOT test number
 496415076613

Result

X Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clips missing (6.1.7 (g) (ii))

Fail Offside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

MOT test number

Result

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



MOT #6 2022-03-16 11:14

MOT test number 214753001304

Result × Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2021-03-15 14:50

MOT test number 250879582440

Result \sqrt{Passed}

MOT #4 2020-03-17 15:59

MOT test number 544915813231

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #3 2020-03-17 09:23

MOT test number 327638094794

Result X Failed

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #2 2019-04-26 14:08

MOT test number 479481016512

CarCheck.co.uk page 4/12



MOT #1 2019-04-24 14:13

MOT test number 867478815323

Result X Failed

Minor Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 33 |
| MOT expiry date | 16 March 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e when miscory | |
|--|-------------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-04-20 |
| Last registration | 2023-03-15 |
| Complete history | See info |



| Registration #1 | 2016-04-20 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2019-04-24 | 20.811 mi |
| Registration #3 | 2019-04-26 | 20.812 mi |
| Registration #4 | 2020-03-17 | 23.144 mi |
| Registration #5 | 2020-03-17 | 23.145 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 19.777 es |

More info >

CarCheck.co.uk page 11/12



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 68% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 66% |
| Video | see crash video |



Dimensions & weight

| Width | 1615 mm |
|---------------------|---------|
| Height | 1460 mm |
| Length | 3465 mm |
| Wheel base | 2340 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1240 kg |

Additional information

| Fuel tank capacity | 35 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 8160720 |

CarCheck.co.uk page 12/12