



E059NFG

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Grey
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg



**MOT history**

MOT #12	2020-09-07 14:27
MOT test number	290789311332
Result	✓ Passed
Next expiry date	2021-09-11
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #11	2020-09-07 14:23
MOT test number	386263870735
Result	✗ Failed
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))

**MOT #10**

2019-09-10 14:53

MOT test number

806965346360

Result

✓ Passed

Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Nail in tyre**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9**

2019-09-10 09:18

MOT test number

987251799760

Result

✗ Failed

Fail Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Nail in tyre**MOT #8**

2018-09-07 10:39

MOT test number

893142060847

Result

✓ Passed

**MOT #7** 2018-09-07 10:39**MOT test number** 631529255835**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #6** 2017-09-09 11:23**MOT test number** 775643780627**Result** ✓ Passed**MOT #5** 2016-09-12 11:56**MOT test number** 648777295203**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-09-08 13:44**MOT test number** 184468078471**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)**MOT #3** 2014-09-04 11:38**MOT test number** 868947644248**Result** ✓ Passed**MOT #2** 2013-08-28 13:21**MOT test number** 948630343233**Result** ✓ Passed**Notice** O/s/f tyre cracking in tread



MOT #1	2012-08-31 14:54
MOT test number	285354642229
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-09
Last registration	2020-09-07
Complete history	See info



Registration #1	2009-09-09	14 mi
Registration #2	2012-08-31	23.814 mi
Registration #3	2013-08-28	29.345 mi
Registration #4	2014-09-04	39.386 mi
Registration #5	2015-09-08	49.645 mi
Registration #6	2016-09-12	62.948 mi
Registration #7	2017-09-09	70.983 mi
Registration #8	2018-09-07	75.277 mi
Registration #9	2019-09-07	75.277 mi
Registration #10	2019-09-07	75.277 mi
Registration #11	2019-09-07	75.277 mi
Registration #12	2019-09-07	75.277 mi
Registration #13	2019-09-07	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 116680