




report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.4 mpg
CO2 emission	264 g/km
CO2 label	M






Internet history

Entry 1

Date	2022-02-25
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-06-13
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	24
Total items failed	23

MOT #19	2022-06-14 09:18
MOT test number	633235982610
Result	✓ Passed
Next expiry date	2023-06-13

MOT #18	2021-01-08 15:33
MOT test number	746986058489
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Chassis corroded also covered in underseal unable to fully inspect prescribed areas
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #17** 2020-11-24 12:41**MOT test number** 210853652693**Result** ✗ Failed

- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced chassis to body mounting (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Chassis corroded also covered in underseal unable to fully inspect prescribed areas
- Fail** Nearside Rear Towbar excessively corroded within 30cm of towbar mounting (6.1.6 (i) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #16 2019-05-31 10:57**MOT test number** 580726703585**Result** ✓ Passed**MOT #15** 2019-05-31 10:57**MOT test number** 330766777091**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

**MOT #14** 2018-10-24 12:21**MOT test number** 226312083757**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2017-12-15 12:32**MOT test number** 400773488487**Result** ✓ Passed**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**MOT #12** 2017-12-13 12:19**MOT test number** 596595348864**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Fail** Rear Drive shaft uj which forms part of the suspension has excessive play in a universal joint propshaft bearing excess play (2.4.G.4b)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)

**MOT #11** 2016-12-10 08:22**MOT test number** 548961523270**Result** ✓ Passed**MOT #10** 2016-12-10 07:16**MOT test number** 549656609444**Result** ✗ Failed**Fail** Registration plate lamp not working both (1.1.C.1d)**MOT #9** 2015-12-05 09:59**MOT test number** 176154649735**Result** ✓ Passed**Advice** Brake pipe slightly corroded all (3.6.B.2c)**MOT #8** 2015-12-02 16:51**MOT test number** 264526594809**Result** ✗ Failed**Advice** Brake pipe slightly corroded all (3.6.B.2c)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front suspension has excessive play in a lower suspension ball joint nsf/osf lower (2.5.B.1a)**MOT #7** 2014-12-02 14:50**MOT test number** 385506234312**Result** ✓ Passed

**MOT #6** 2014-12-02 12:18**MOT test number** 309396434348**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #5** 2013-08-29 20:32**MOT test number** 527111743207**Result** ✓ Passed**MOT #4** 2012-06-12 15:32**MOT test number** 967044362131**Result** ✓ Passed**MOT #3** 2011-11-11 11:24**MOT test number** 829965111309**Result** ✓ Passed**Advice** Offside Rear wheel bearing has slight play (2.6.2)**MOT #2** 2010-11-18 09:46**MOT test number** 103232520349**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2009-11-10 15:04
MOT test number	724964319324
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-31
Last registration	2022-06-14
Complete history	See info



Registration #1	2006-10-31	25 mi
Registration #2	2009-11-10	56.373 mi
Registration #3	2010-11-18	73.730 mi
Registration #4	2011-11-11	82.760 mi
Registration #5	2012-06-12	87.360 mi
Registration #6	2013-08-29	98.126 mi
Registration #7	2014-12-02	101.964 mi
Registration #8	2014-12-02	101.964 mi
Registration #9	2015-12-02	105.245 mi
Registration #10	2015-12-05	105.259 mi
Registration #11	2016-12-10	116.314 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi
Registration #18	2019-05-29	151.377 mi
Registration #19	2019-05-29	151.377 mi
Registration #20	2019-05-29	151.377 mi
Registration #21	2019-05-29	151.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2267 kg
Max. allowed weight	2793 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	778382