



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA DYNAMIC
Colour	Black
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	133 g/km
CO2 label	E





MOT history

MOT expiry date	2025-03-12
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	65
Total items failed	6

MOT #23	2024-03-13 10:05
MOT test number	452133442550
Result	✓ Passed
Next expiry date	2025-03-12

MOT #22	2024-03-07 11:44
MOT test number	216750442265
Result	✗ Failed
MAJOR Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))	
MAJOR Offside Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR Nearside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))	
DANGEROUS Offside Rear Suspension spring mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected (5.3.6 (a) (ii))	
MAJOR Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))	
MAJOR Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))	
MAJOR Offside Front Service brake excessively binding (1.2.1 (f))	
MAJOR Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))	

MOT #21	2023-03-08 14:03
MOT test number	832213644410
Result	✓ Passed

**MOT #20** 2023-03-07 15:08**MOT test number** 345969949611**Result** ✗ Failed

- MAJOR** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #19 2022-03-08 15:28**MOT test number** 589277324173**Result** ✓ Passed

**MOT #18**

2022-02-22 15:51

MOT test number

597015135976

Result**✗ Failed**

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- MAJOR** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Front Exhaust system insecure (6.1.2 (a))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Offside Obligatory mirror insecure (3.3 (b) (ii))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

MOT #17

2021-02-24 17:23

MOT test number

750651001214

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #16	2021-02-17 08:58
MOT test number	891246579157
Result	✗ Failed
MAJOR	Oil leaking excessively from engine oil pan (8.4.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-10-16 14:40
MOT test number	216386062613
Result	✓ Passed
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Under tray fitted obscuring underside brake pipes

**MOT #14**

2019-10-16 11:26

MOT test number

863292718981

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Under tray fitted obscuring underside brake pipes
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

MOT #13

2019-01-25 10:55

MOT test number

963910587385

Result**✓ Passed**

- Advice** Central Front Exhaust has a minor leak of exhaust gases at flexi (6.1.2 (a))

**MOT #12** 2019-01-25 10:55**MOT test number** 982469691875**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Central Front Exhaust has a minor leak of exhaust gases at flexi (6.1.2 (a))**MOT #11** 2018-01-29 14:51**MOT test number** 196276377512**Result** ✓ Passed**MOT #10** 2018-01-29 14:51**MOT test number** 484216802920**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2017-01-30 10:11**MOT test number** 759874186063**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit running off inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit running off inner edge (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2017-01-30 10:11**MOT test number** 492859018811**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit running off inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit running off inner edge (4.1.E.1)**MOT #7** 2016-01-26 15:41**MOT test number** 350860821447**Result** ✓ Passed**Advice** Rear silencer deteriorated**MOT #6** 2016-01-26 11:33**MOT test number** 718222747211**Result** ✗ Failed**Advice** Rear silencer deteriorated**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-05-12 16:18**MOT test number** 105552035147**Result** ✓ Passed**MOT #4** 2015-05-09 13:08**MOT test number** 178359225129**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)



MOT #3	2014-02-08 11:37
MOT test number	767279734039
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-02-08 11:03
MOT test number	189679933036
Result	✓ Passed

MOT #1	2011-11-03 11:38
MOT test number	149857001366
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 March 2025

Tax status		Valid until 1 September
Days left		125
MOT expiry date		12 March 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-10-31
Last registration	2024-03-13
Complete history	See info



Registration #1	2008-10-31	26 mi
Registration #2	2011-11-03	7.647 mi
Registration #3	2013-02-08	11.263 mi
Registration #4	2014-02-08	17.563 mi
Registration #5	2015-05-09	29.951 mi
Registration #6	2015-05-12	29.955 mi
Registration #7	2016-01-26	35.923 mi
Registration #8	2016-01-26	35.926 mi
Registration #9	2017-01-30	41.396 mi
Registration #10	2017-01-30	41.396 mi
Registration #11	2018-01-29	46.341 mi
Registration #12	2018-01-29	46.341 mi
Registration #13	2019-01-29	51.317 mi
Registration #14	2019-01-29	51.317 mi
Registration #15	2020-01-29	56.293 mi
Registration #16	2020-01-29	56.293 mi
Registration #17	2021-01-29	61.269 mi
Registration #18	2021-01-29	61.269 mi
Registration #19	2022-01-29	66.245 mi
Registration #20	2022-01-29	66.245 mi
Registration #21	2023-01-29	71.221 mi
Registration #22	2023-01-29	71.221 mi
Registration #23	2024-01-29	76.197 mi
Registration #24	2024-01-29	76.197 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number	4456931
---------------	---------