





report date: 2024-03-29

#### General information

Make	ТОУОТА
Model	AVENSIS D-4D BUSINESS EDITION
Colour	Grey
Year of manufacture	2015
Top speed	115 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



### Internet history

_		•		_	-
-	n	т	rv	,	

Liid y I	
Date	2021-06-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-16
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	19
Total items failed	1

	2023-09-08 15:18
umber	581746490420
	✓ Passed
date	2024-09-16
offside Front Suspension arm ball joint dust cover severely deteriorated	(5.3.4 (b) (i))
Nearside Front Macpherson strut corroded but not seriously weakened (	(5.3.3 (b) (i))
earside Front Suspension arm ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))
Offside Front Macpherson strut corroded but not seriously weakened (5	.3.3 (b) (i))
	Nearside Front Macpherson strut corroded but not seriously weakened learside Front Suspension arm ball joint dust cover severely deteriorate

MOT #7	2	022-09-07 14:10
MOT test n	umber	996791417018
Result		✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (	b) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4	(b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**YS15UFE** 

report date: 2024-03-29

**MOT** #6 2022-09-07 14:10 953282928439 **MOT** test number Result × Failed Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-09-17 14:16
MOT test number	698303186497
Result	✓ Passed
MOT #4	2021-02-12 10:54
MOT test number	177718712689
Result	✓ Passed
MOT #3	2020-02-13 16:00
MOT test number	540404560886
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2019-02-15 09:36
MOT test number	984628044450
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



**MOT #1** 2018-03-07 11:40

**MOT test number** 373864260083

CarCheck.co.uk page 5/12





report date: 2024-03-29

#### Tax & MOT check





**Expires:** 16 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-


CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



**YS15UFE** 

report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this TOYOTA had different number plates.	
See in this eneck is this 1919 in that amerene names places	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



**YS15UFE** 

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-06-30
Last registration	2023-09-08
Complete history	See info



Registration #1	2015-06-30	29 mi
Registration #2	2018-03-07	27.844 mi
Registration #3	2019-02-15	45.824 mi
Registration #4	2020-02-13	65.630 mi
Registration #5	2021-02-12	77.608 mi
Registration #6		
Registration #0		
Registration #7		11.777 es
-		11.00 m
Registration #7		11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
60567	
60569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4820 mm
Wheel base	2700 mm
Kerb weight	1535 kg
Max. allowed weight	2040 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	ge 12/12

Number of axles 2

Engine number N472309264