



General information

Make	VOLKSWAGEN
Model	POLO GT TSI DSG
Colour	Black
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-06-09
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	28
Total items failed	22

MOT #19	2024-01-17 17:25
MOT test number	648449432790
Result	✓ Passed
Next expiry date	2025-02-01

MOT #18	2024-01-17 14:36
MOT test number	160221207629

Result	✗ Failed
--------	----------

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #17	2023-01-28 12:24
MOT test number	191447410706

Result	✓ Passed
--------	----------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2022-01-31 17:41**MOT test number** 301171002544**Result** ✓ Passed**MOT #15** 2022-01-31 14:46**MOT test number** 928266486036**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #14** 2021-01-30 14:39**MOT test number** 570507751971**Result** ✓ Passed**Advice** Offside Front Inner Play in steering rack inner joint(s)**MOT #13** 2021-01-29 15:06**MOT test number** 737335131221**Result** ✗ Failed**Advice** Offside Front Inner Play in steering rack inner joint(s)**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12**

2020-02-01 15:33

MOT test number

203082211034

Result

✓ Passed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2019-02-02 12:50

MOT test number

385140979352

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases back box corroded and has a leak behind (6.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10**

2019-02-02 10:20

MOT test number

699917142569

Result

✗ Failed

Advice Nearside Rear Exhaust has a minor leak of exhaust gases back box corroded and has a leak behind (6.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9**

2017-10-14 13:26

MOT test number

956099544306

Result

✓ Passed

**MOT #8** 2017-10-14 09:27**MOT test number** 604284408228**Result** ✗ Failed**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Front Exhaust has a major leak of exhaust gases flexi (7.1.2)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #7** 2016-10-10 11:32**MOT test number** 329869549643**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened s (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2015-10-10 08:33**MOT test number** 446644106904**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #5** 2015-10-09 15:02**MOT test number** 303146574605**Result** ✗ Failed

- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2014-10-10 15:59**MOT test number** 358703084211**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front e rear discs corroded
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-10-10 09:43**MOT test number** 989033484253**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front e rear discs corroded
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #2	2013-10-16 17:00
MOT test number	736849683220
Result	✓ Passed
MOT #1	2012-10-13 12:31
MOT test number	399447382470
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
29 March 2024

✓

MOT

Expires:
1 February 2025

Tax status	Expired at 29 March 2024
Days left	32 days too late
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-15
Last registration	2024-01-17
Complete history	See info



Registration #1	2009-10-15	26 mi
Registration #2	2012-10-13	42.942 mi
Registration #3	2013-10-16	55.816 mi
Registration #4	2014-10-10	62.465 mi
Registration #5	2014-10-10	62.465 mi
Registration #6	2015-10-09	66.267 mi
Registration #7	2015-10-10	66.267 mi
Registration #8	2016-10-10	69.455 mi
Registration #9	2017-10-14	71.174 mi
Registration #10	2017-10-14	71.182 mi
Registration #11	2019-02-02	72.096 mi
Registration #12	2019-02-02	72.096 mi
Registration #13	2019-02-02	72.096 mi
Registration #14	2019-02-02	72.096 mi
Registration #15	2019-02-02	72.096 mi
Registration #16	2019-02-02	72.096 mi
Registration #17	2019-02-02	72.096 mi
Registration #18	2019-02-02	72.096 mi
Registration #19	2019-02-02	72.096 mi
Registration #20	2019-02-02	72.096 mi
Registration #21	2019-02-02	72.096 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1286 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAV 129813