



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Grey
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D






Internet history

Entry 4

Date	2021-08-10
Pictures	49
Listing price	View report



source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 3

Date	2021-07-23
Pictures	7
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 2

Date	2021-07-10
Pictures	1
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-09
------	------------

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-11
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #4	2023-12-12 12:56
MOT test number	838347698716
Result	✓ Passed
Next expiry date	2024-12-11
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3	2022-05-24 11:51
MOT test number	562777019969
Result	✓ Passed
Advice	Engine covers and undertray fitted

MOT #2	2021-05-17 08:32
MOT test number	105627360194
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #12021-05-15 11:27

MOT test number815813481003

Result		✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
11 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY180VB
Plate since	2019-03-28
Current registration	YY180VB
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-25
Last registration	2023-12-12
Complete history	See info



Registration #1	2018-05-25	27 mi
Registration #2	2021-05-15	28.489 mi
Registration #3	2021-05-17	28.489 mi
Registration #4	2022-05-20	29.277 mi
Registration #5	2022-05-20	29.277 mi
Registration #6	2022-05-20	29.277 mi
Registration #7	2022-05-20	29.277 mi
Registration #8	2022-05-20	29.277 mi
Registration #9	2022-05-20	29.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1417 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2348614