





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	308 E-HDI XY
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

## Entry 1

Date 2021-02-03

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



LB64KBU report date: 2024-03-29

MOT history

MOT expiry date	2024-12-13
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	10

MOT #10	2023-12-14 10:01
MOT test number	133968664831
Result	<b>✓</b> Passed
Next expiry date	2024-12-13
Advice Front Suspension arm pin or bush worn but not resulting in excessi (a) (i))	ive movement both sides (5.3.4

MOT #9	2023-02-23 11:49
MOT test number	803664028454
Result	<b>✓</b> Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not resu (5.3.4 (a) (i))  Advice Offside Front Lower Suspension arm pin or bush worn but not resulti (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



Fail

LB64KBU

report date: 2024-03-29

**MOT** #8 2023-02-17 15:32 **MOT** test number 412403579171 Result **X** Failed Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2022-02-18 16:08
MOT test number	579117718637
Result	<b>✓</b> Passed

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

		V
MOT #	6	2022-02-04 12:39
MOT te	est number	509970711047
Result		<b>×</b> Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2021-02-04 17:02

**MOT test number** 292778265947

**Result** ✓ Passed

MOT #4 2020-10-01 14:22

MOT test number 233698575480

**Result** ✓ Passed

**Advice** Front Tyre worn close to legal limit/worn on edge nearside and offside (5.2.3 (e))

MOT #3 2019-02-20 14:47

MOT test number 614940990684

**Result** 
✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front sharp edge on wing

MOT #2 2018-02-22 09:01

MOT test number 681111235330

**Result** ✓ Passed

MOT #1 2018-02-22 09:01

**MOT test number** 823103537699

**Result** X Failed

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 5/12



LB64KBU report date: 2024-03-29

Tax & MOT check





Expires: 13 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	13 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. about of pliates faste since

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-02-25
Last registration	2023-12-14
Complete history	See info



Registration #1	2015-02-25	16 mi
Registration #2	2018-02-22	41.213 mi
Registration #3	2018-02-22	41.213 mi
Registration #4	2019-02-20	54.511 mi
Registration #5	2020-10-01	60.152 mi
Registration #6		77,777 44
Registration #7		11.777 es
Registration #8		77,777 44
Registration #9		71.777 66
Registration #10		77,777 44
Registration #11		11.177 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	78%
Pedestrian	61%
Safety systems	83%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	2004 mm
Height	1460 mm
Length	3965 mm
Wheel base	2538 mm
Kerb weight	1268 kg
Max. allowed weight	1665 kg

# Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 pa	age 12/12

Number of axles 2

Engine number JBFS0072980