



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA 12V EXPRESSION TWINPORT
Colour	Blue
Year of manufacture	-
Top speed	88 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	58 BHP
Max. torque	85 Nm at 3.800 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-12
Pictures	25
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #21	2022-06-20 11:04
MOT test number	692207979070
Result	✓ Passed
Next expiry date	2023-06-23
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2022-06-15 08:24
MOT test number	909521113917
Result	✗ Failed
Fail	Offside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
Fail	Nearside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2021-06-24 11:20
MOT test number	910288259350
Result	✓ Passed
Advice	Front bumper slightly damaged

MOT #18	2020-06-24 13:21
MOT test number	410638460330
Result	✓ Passed

MOT #17	2019-06-24 12:45
MOT test number	964529361407
Result	✓ Passed

**MOT #16** 2019-06-24 12:25**MOT test number** 141513475313**Result** ✗ Failed

- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #15 2018-04-19 09:20**MOT test number** 624655455899**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both side (3.5.1i)
- Advice** Front Macpherson strut has slight movement at the upper attachment both side (2.5.A.1c)

MOT #14 2018-04-18 15:35**MOT test number** 514274009826**Result** ✗ Failed

- Fail** Front Tyre tread depth below requirements of 1.6mm both side (4.1.E.1)
- Fail** Headlamp not working on dipped beam x2 (1.7.5a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both side (3.5.1i)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Front Macpherson strut has slight movement at the upper attachment both side (2.5.A.1c)

MOT #13 2017-05-15 09:15**MOT test number** 775538110412**Result** ✓ Passed

**MOT #12** 2017-05-15 08:38**MOT test number** 245789391624**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #11** 2016-06-06 10:17**MOT test number** 237014544963**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #10** 2015-05-26 10:15**MOT test number** 958606145150**Result** ✓ Passed**Advice** Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #9** 2015-05-26 10:15**MOT test number** 647406745140**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #8** 2014-05-29 14:58**MOT test number** 558779044126**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2013-06-10 13:50**MOT test number** 688321963174**Result** ✓ Passed**MOT #6** 2012-05-26 09:12**MOT test number** 746887042147**Result** ✓ Passed

**MOT #5** 2011-07-11 08:35**MOT test number** 226682391184**Result** ✓ Passed**Notice** Offside front tyre worn on edges.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Tyre size 155/65R14 75T**MOT #4** 2010-07-13 10:05**MOT test number** 473924990115**Result** ✓ Passed**MOT #3** 2009-07-07 14:44**MOT test number** 844278589142**Result** ✓ Passed**MOT #2** 2009-07-07 14:44**MOT test number** 124438189183**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2008-07-14 11:19**MOT test number** 300196598124**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	BT05YCP
Plate since	2024-03-29
Current registration	BT05YCP
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-06-29
Last registration	2022-06-20
Complete history	See info



Registration #1	2005-06-29	12 mi
Registration #2	2008-07-14	14.566 mi
Registration #3	2009-07-07	16.407 mi
Registration #4	2010-07-13	18.345 mi
Registration #5	2011-07-11	19.294 mi
Registration #6	2012-05-26	23.304 mi
Registration #7	2013-06-10	32.960 mi
Registration #8	2014-05-29	41.860 mi
Registration #9	2015-05-26	58.468 mi
Registration #10	2016-06-06	73.959 mi
Registration #11	2017-05-15	78.900 mi
Registration #12	2018-05-20	85.337 mi
Registration #13	2019-05-20	91.774 mi
Registration #14	2020-05-20	98.211 mi
Registration #15	2021-05-20	104.648 mi
Registration #16	2022-05-20	111.085 mi
Registration #17	2023-05-20	117.522 mi
Registration #18	2024-05-20	123.959 mi
Registration #19	2025-05-20	130.396 mi
Registration #20	2026-05-20	136.833 mi
Registration #21	2027-05-20	143.270 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	965 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19EH5413