





report date: 2024-03-29

General information

Make	KIA
Model	SOUL CRDI ECHO
Colour	Black
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-26

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-09
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #14	2023-11-22 11:05
MOT test number	694338106529
Result	✓ Passed
Next expiry date	2024-12-09

MOT #13		2022-12-06 11:30
MOT test	number	595803740098
Result		✓ Passed
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3	s (e))

MOT #12	2021-12-10 13:16
MOT test number	495576309909
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT test number

Result

Advice
Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i))

Advice
Nearside Front Tyre has a cut but not deep enough to reach the ply or cords in tread (5.2.3 (d) (i))

Advice
Brake pedal wearing smooth (1.1.2 (c))

MOT #10 2021-07-16 08:14 **MOT** test number 159831498949 Result × Failed Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords in tread (5.2.3 (d) (i)) Advice Rear Coil spring corroded n/s & o/s (5.3.1 (b) (i)) Advice Brake pedal wearing smooth (1.1.2 (c)) **Advice** Restricted free movement on o/s/f wheel Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **Advice** Nearside Rear Nail in tyre

MOT #9

MOT test number

Result

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



Fail

(2.1.3 (g) (ii))

LC11CAE report date: 2024-03-29

2020-07-16 10:45 **MOT #8** 639921279846 **MOT test number** Result × Failed **Advice** N/s rear wheel slightly binding Nearside Rear Nail in tyre Advice Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt

MOT #7		2010 04 26 00:17
MOT #7		2019-04-26 09:17
MOT test	number	962083034832
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge & outer edges (5.2.3 (e))	
Advice Offside Rear Brake hose has slight corrosion to ferrule on metal part of flexible hose connecting to front part of hose (1.1.12 (f) (i))		

MOT #6	2018-04-04 08:51
MOT test number	720160483546
Result	✓ Passed
MOT #5	2017-04-28 11:58
MOT test number	420073080899
Result	✓ Passed
Advice Corrosion on exhaust system	

CarCheck.co.uk page 5/13



MOT test number

692453625994

Result

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Corrosion on exhaust system

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2016-04-20 08:25 **MOT** test number 514982810871 Result ✓ Passed MOT #2 2015-04-29 14:42 **MOT** test number 295799415175 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Exhaust excessivly corroded **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-04-11 09:47
MOT test number	777201504137
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	9 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



\sim		
Owner	hictory	7
OWITCE	HIJLOH	٧

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report have the current and the full report have the current and the full report have the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have the current and current and previous owner(s) have the current and c</u>	

THE STATE OF THE S	

	More info >
<u></u>	
Plate changes	
Cooling their shoots if their IVIA had different mumber plates	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK O
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-30
Last registration	2023-11-22
Complete history	See info



Registration #1	2011-04-30	9 mi
Registration #2	2014-04-11	33.503 mi
Registration #3	2015-04-29	44.781 mi
Registration #4	2016-04-20	53.881 mi
Registration #5	2017-04-28	62.314 mi
Registration #6	2017-04-28	62.314 mi
Registration #7	2018-04-04	71.476 mi
Registration #8	2019-04-26	77.391 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 ms
Registration #16		10.777 au

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1429 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number D4FBAH532535