





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE XKR
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	420 BHP
Max. torque	560 Nm at 4.000 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	294 g/km
CO2 label	M



CarCheck.co.uk page 1/13



S77YPR

report date: 2024-03-28

Internet history

Entry 2

Date 2021-12-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-12-12

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-08-10
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	13
Total items failed	8

MOT #14	2021-08-11 13:30
MOT test number	646928876428
Result	✓ Passed
Next expiry date	2022-08-10

MOT #13	2021-08-11 11:20
MOT test number	986169953581
Result	X Failed
Fail Horn not working (7.7 (a) (ii))	

MOT #12	202	0-07-30 12:34
MOT test	number 3	38449580958
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii))
Advice Nearside Front Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii))		ii))

CarCheck.co.uk page 3/13



S77YPR

report date: 2024-03-28

MOT #11 2020-07-29 15:08 **MOT** test number 999503171233 Result × Failed Fail Offside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii)) Offside Headlamp not working on main beam (4.1.1 (a) (ii)) Fail **Advice** Nearside Front Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii)) Horn not working (7.7 (a) (ii)) **Fail**

MOT test number

Fesult

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #9

MOT test number

Result

Advice Engine bay covers and undertrays fitted

MOT test number

Result

Advice Front wiper blades worn and split

Advice Offside front tyre cracked and perished on outer edge

Advice Engine covers and under trays fitted

CarCheck.co.uk page 4/13



MOT #7

S77YPR report date: 2024-03-28

2016-07-21 08:12

MOT test number 121804435437

Result \(\sqrt{Passed} \)

Advice Brake disc worn, pitted or scored, but not seriously weakened Front and Rear (3.5.1i)

MOT #6 2015-07-01 16:42

MOT test number 326042585182

MOT #5 2014-07-18 13:17

MOT test number 807479994173

Result ✓ Passed

MOT #4 2013-07-22 16:50

MOT test number 227863903220

MOT #3 2013-07-19 15:30

MOT test number 287390703283

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Coolant leak

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #2 2012-07-20 16:34

MOT test number 476472302232

CarCheck.co.uk page 5/13



MOT #1 2011-07-26 17:23

MOT test number 599887501253

CarCheck.co.uk page 6/13



Tax & MOT check



Tax expired: 3 February 2022

X MOT

Expired: 10 August 2022

Tax status	Expired at 3 February 2022
Days left	815 days too late
MOT expiry date	10 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		λ R

	More info	>
Plate changes See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-29
Last registration	2021-08-11
Complete history	See info



Registration #1	2007-10-29	8 mi
Registration #2	2011-07-26	11.963 mi
Registration #3	2012-07-20	17.475 mi
Registration #4	2013-07-19	24.297 mi
Registration #5	2013-07-22	24.299 mi
Registration #6	2014-07-18	29.597 mi
Registration #7	2015-07-01	36.299 mi
Registration #8	2016-07-21	49.153 mi
Registration #9	2017-07-26	55.263 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1715 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	07020117059G

CarCheck.co.uk page 13/13