



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | AUDI |
| Model | A4 TDI QUATTRO SE TECHNIK |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 140 mph |
| 0 - 60 mph | 7.9 seconds |
| Gearbox | 7 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 174 BHP |
| Max. torque | 380 Nm at 2.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-25 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-07 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 19 |
| Total items failed | 0 |

| | |
|------------------|------------------|
| MOT #9 | 2023-07-03 08:28 |
| MOT test number | 524510854808 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-07 |

| | |
|-----------------|--|
| MOT #8 | 2022-07-05 16:19 |
| MOT test number | 205473383249 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall damaged. (5.2.3 (d) (i)) |

| | |
|-----------------|---|
| MOT #7 | 2022-07-04 09:26 |
| MOT test number | 242771413861 |
| Result | ✗ Failed |
| MAJOR | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) |
| MAJOR | Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall damaged. (5.2.3 (d) (i)) |

| | |
|-----------------|------------------|
| MOT #6 | 2021-07-08 15:33 |
| MOT test number | 111006219036 |
| Result | ✓ Passed |

**MOT #5**

2021-04-19 16:28

MOT test number

657500258699

Result

✓ Passed

- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #4

2020-08-25 09:45

MOT test number

917417433940

Result

✓ Passed

MOT #3

2020-07-10 15:00

MOT test number

799917799696

Result

✗ Failed

- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Dipswitch does not operate immediately when selected on main beam (4.1.3 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Dipswitch does not operate immediately when selected on dipped beam (4.1.3 (b))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



| | |
|-----------------|------------------|
| MOT #2 | 2019-04-17 10:33 |
| MOT test number | 338869056190 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2018-05-17 14:16 |
| MOT test number | 817269243343 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 7 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-04-29 |
| Last registration | 2023-07-03 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-04-29 | 16 mi |
| Registration #2 | 2018-05-17 | 28.259 mi |
| Registration #3 | 2019-04-17 | 34.011 mi |
| Registration #4 | 2020-07-10 | 44.774 mi |
| Registration #5 | 2020-08-25 | 46.191 mi |
| Registration #6 | 2021-04-19 | 50.980 mi |
| Registration #7 | 2022-05-20 | 55.777 mi |
| Registration #8 | 2022-05-20 | 55.777 mi |
| Registration #9 | 2022-05-20 | 55.777 mi |
| Registration #10 | 2022-05-20 | 55.777 mi |
| Registration #11 | 2023-07-03 | 55.777 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 93% |
| Children | 84% |
| Pedestrian | 39% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2040 mm |
| Height | 1427 mm |
| Length | 4701 mm |
| Wheel base | 2808 mm |
| Kerb weight | 1595 kg |
| Max. allowed weight | 2145 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 61 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | CGLC472934 |