



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | FORD |
| Model | FOCUS C-MAX ZETEC |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 116 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 113 BHP |
| Max. torque | 155 Nm at 4.150 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 42.8 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-08 |
| Pictures | 6 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #18 | 2023-07-10 16:05 |
| MOT test number | 430702430575 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-17 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Rear Coil spring corroded Both (5.3.1 (b) (i)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |

| | |
|------------------------|---|
| MOT #17 | 2022-07-18 07:50 |
| MOT test number | 755262409635 |
| Result | ✓ Passed |
| Advice | Nearside Front Nail in tyre |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|------------------------|---|
| MOT #16 | 2022-07-09 10:19 |
| MOT test number | 804665429659 |
| Result | ✗ Failed |
| Fail | Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Fail | Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Minor | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Fail | Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i)) |
| Advice | Nearside Front Nail in tyre |

**MOT #15** 2021-07-06 15:24**MOT test number** 399542559915**Result** ✓ Passed**MOT #14** 2020-07-14 07:42**MOT test number** 414044223215**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-07-05 07:31**MOT test number** 183848301255**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #12** 2018-07-10 07:54**MOT test number** 667710031184**Result** ✓ Passed**MOT #11** 2017-07-11 07:55**MOT test number** 884649911215**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-07-12 07:24**MOT test number** 506857704556**Result** ✓ Passed

**MOT #9** 2015-07-08 08:37**MOT test number** 225359285100**Result** ✓ Passed**MOT #8** 2014-07-07 08:36**MOT test number** 806408384162**Result** ✓ Passed**MOT #7** 2013-07-16 16:52**MOT test number** 876397193173**Result** ✓ Passed**MOT #6** 2012-11-15 09:26**MOT test number** 527780622328**Result** ✓ Passed**Notice** Child seat fitted to near side rear outer seat**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Damage and marks to bodywork on rear bumper and near side rear and off side front**Notice** Rear bumper reflectors insecure**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Rear tyres cracking**MOT #5** 2011-11-15 11:47**MOT test number** 366659511314**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2011-11-15 11:47**MOT test number** 265869611336**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2010-11-15 10:30**MOT test number** 442859610405**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-11-13 09:45**MOT test number** 574827719372**Result** ✓ Passed**MOT #1** 2008-11-12 11:16**MOT test number** 613637518316**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YE55BWL |
| Plate since | 2019-09-28 |
| Current registration | YE55BWL |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2005-12-22 |
| Last registration | 2023-07-10 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2005-12-22 | 23 mi |
| Registration #2 | 2008-11-12 | 12.478 mi |
| Registration #3 | 2009-11-13 | 15.977 mi |
| Registration #4 | 2010-11-15 | 20.954 mi |
| Registration #5 | 2011-11-15 | 25.720 mi |
| Registration #6 | 2012-11-15 | 29.998 mi |
| Registration #7 | 2013-07-16 | 32.334 mi |
| Registration #8 | 2014-07-07 | 44.815 mi |
| Registration #9 | 2015-07-08 | 56.583 mi |
| Registration #10 | 2016-07-12 | 67.059 mi |
| Registration #11 | 2017-07-12 | 77.536 mi |
| Registration #12 | 2018-07-12 | 88.013 mi |
| Registration #13 | 2019-07-12 | 98.490 mi |
| Registration #14 | 2020-07-12 | 108.967 mi |
| Registration #15 | 2021-07-12 | 119.444 mi |
| Registration #16 | 2022-07-12 | 129.921 mi |
| Registration #17 | 2023-07-10 | 140.398 mi |
| Registration #18 | 2024-03-28 | 150.875 mi |
| Registration #19 | 2024-03-28 | 161.352 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1825 mm |
| Height | 1595 mm |
| Length | 4333 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1371 kg |
| Max. allowed weight | 1870 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 5R43462 |