



**MX57YRW**

report date: 2024-03-28

General information

Make	FORD
Model	C-MAX STYLE 90
Colour	Silver
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	56 %
MOT passed	14
Failed MOT tests	11
Total advice items	40
Total items failed	12

MOT #252024-02-09 11:00

MOT test number957333614975

Result✓ Passed

Next expiry date2025-02-13

- AdviceRear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceCentral Front Oil leak, but not excessive (8.4.1 (a) (i))
- AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceRear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #24**

2024-02-08 09:35

**MOT test number**

191501466007

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #23**

2023-02-14 13:25

**MOT test number**

526830930299

**Result****✓ Passed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #22**

2023-02-12 14:13

**MOT test number**

311199915388

**Result****✗ Failed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

**MOT #21** 2021-12-21 10:27**MOT test number** 369667685181**Result** ✓ Passed**MOT #20** 2021-12-15 16:50**MOT test number** 813703903237**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**MOT #19** 2020-12-21 13:34**MOT test number** 379380192556**Result** ✓ Passed**MOT #18** 2020-12-21 13:34**MOT test number** 472216960054**Result** ✗ Failed**Pass with rectification** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Pass with rectification** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #17** 2020-11-03 15:10**MOT test number** 910734920904**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear most (5.3.4 (a) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear most (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #16** 2019-10-15 09:41**MOT test number** 168491078468**Result** ✓ Passed**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Advice** Engine under try loose**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Center exhust sheild loose**MOT #15** 2019-10-15 09:41**MOT test number** 851377412723**Result** ✗ Failed**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine under try loose**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Advice** Center exhust sheild loose**MOT #14** 2018-10-24 11:38**MOT test number** 476842720499**Result** ✓ Passed**MOT #13** 2018-10-24 11:38**MOT test number** 930888954161**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #12** 2017-10-20 12:26**MOT test number** 779535312215**Result** ✓ Passed**MOT #11** 2017-10-19 10:06**MOT test number** 412565623608**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #10** 2016-10-21 10:45**MOT test number** 411305349282**Result** ✓ Passed**MOT #9** 2016-10-21 10:45**MOT test number** 940313607429**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2015-10-20 00:00**MOT test number** 449915265069**Result** ✓ Passed**MOT #7** 2014-10-30 15:33**MOT test number** 607183904398**Result** ✓ Passed

**MOT #6** 2014-10-30 11:16**MOT test number** 407233704347**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #5** 2013-11-05 16:15**MOT test number** 439349403397**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** N/s/f tyre slightly worn on inner edge**MOT #4** 2013-11-04 11:38**MOT test number** 955308803302**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Headlamp insecure (1.7.3)**Notice** N/s/f tyre slightly worn on inner edge**MOT #3** 2013-02-15 12:28**MOT test number** 737806943021**Result** ✓ Passed**MOT #2** 2012-02-17 09:15**MOT test number** 159748242082**Result** ✓ Passed





MOT #1	2011-01-28 09:19
MOT test number	968028921058
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
13 February 2025

Tax status		Valid until 1 February
Days left		278
MOT expiry date		13 February 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-09-29
Current registration	 XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2008-09-01
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2008-09-01	15 mi
Registration #2	2011-01-28	27.504 mi
Registration #3	2012-02-17	38.369 mi
Registration #4	2013-02-15	52.819 mi
Registration #5	2013-11-04	60.680 mi
Registration #6	2013-11-05	60.685 mi
Registration #7	2014-10-30	68.049 mi
Registration #8	2014-10-30	68.051 mi
Registration #9	2015-10-20	75.200 mi
Registration #10	2016-10-21	82.737 mi
Registration #11	2016-10-21	82.737 mi
Registration #12	2017-10-19	90.038 mi
Registration #13	2017-10-20	90.040 mi
Registration #14	2018-10-24	97.113 mi
Registration #15	2019-05-29	97.113 mi
Registration #16	2019-05-29	97.113 mi
Registration #17	2019-05-29	97.113 mi
Registration #18	2019-05-29	97.113 mi
Registration #19	2019-05-29	97.113 mi
Registration #20	2019-05-29	97.113 mi
Registration #21	2019-05-29	97.113 mi
Registration #22	2019-05-29	97.113 mi
Registration #23	2019-05-29	97.113 mi
Registration #24	2019-05-29	97.113 mi
Registration #25	2019-05-29	97.113 mi
Registration #26	2019-05-29	97.113 mi

More info >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

7M61502