





report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Black
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 сс
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-08-18

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

51 .	2021 00 12	
Date	2021-08-12	

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-19
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #10	2023-08-08 08:16
MOT test number	894991840411
Result	✓ Passed
Next expiry date	2024-08-19

MOT #9		2022-08-05 08:53
MOT test no	umber	336638070178
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2021-08-20 12:03
MOT test number	434447999195
Result	√ Passed

MOT #7	2020-12-09 11:07
MOT test number	787563036487
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #6 2020-01-21 14:23

MOT test number 778115329579

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2020-01-21 14:23

MOT test number 224787480631

Result X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2019-08-24 10:14

MOT test number 259505878793

Result ✓ Passed

MOT #3 2018-09-05 14:25

MOT test number 535281135595

Result \(\sqrt{Passed} \)

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Park brake only just met requirements

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2

MOT test number

Result

Advice Offside Rear Nail in tyre

MOT #1

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
Current registration	RIV.
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-08-29
Last registration	2023-08-08
Complete history	See info



Registration #1	2013-08-29	10 mi
Registration #2	2016-08-31	26.183 mi
Registration #3	2017-09-08	36.813 mi
Registration #4	2018-09-05	45.036 mi
Registration #5	2019-08-24	50.893 mi
Registration #6	2020-01-21	52.545 mi
Registration #7	2020-01-21	52.545 mi
Registration #8		11.117 es
Registration #9		11.777 mi
Registration #10		11.177 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		9.777 sc

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12,