





report date: 2024-03-28

General information

Make	FIAT
Model	500C LOUNGE
Colour	Purple
Year of manufacture	2010
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1


Date 2021-10-16

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1010		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-06-15
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #14	2023-06-16 14:31
MOT test number	980348135388
Result	✓ Passed
Next expiry date	2024-06-15

MOT #13	2022-04-28 12:43
MOT test number	848903135861
Result	√ Passed

MOT #12		2021-03-12 15:59
MOT test	number	660426488198
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #11	2021-03-12 15:59
MOT test number	691306783298
Result	▼ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice Offside Rear Coi	spring corroded (5.3.1 (b) (i))
Advice Nearside Rear C	pil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 3/13



(e))

KN60LNA report date: 2024-03-28

MOT #10 2020-03-10 14:04

MOT test number 817819248329

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

Advice Coil spring corroded all 4 (5.3.1 (b) (i))

MOT #9 2019-03-08 15:27

MOT test number 282361141648

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge TYRE WORN ON INNER EDGE (5.2.3

MOT #8 2018-03-09 16:43

MOT test number 508705756014

Result \(\sqrt{Passed} \)

MOT #7 2018-03-09 15:39

MOT test number 875083507445

Result ★ Failed

Fail Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Fail Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

MOT #6 2017-11-13 13:37

MOT test number 949823342448

Advice Nearside front tyre has outside wall damage

Advice Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #5 2017-11-09 10:38

MOT test number 356256421417

Result X Failed

Advice Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside front tyre has outside wall damage

MOT #4 2016-10-13 10:24

MOT test number 177810490524

Result ✓ Passed

MOT #3 2015-09-25 08:41

MOT test number 703781914495

Result

Passed

Advice Rear exhaust box outer casing deterioated

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice N/s front tyre inner wall damaged,

Advice Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #2 2014-10-07 09:20

MOT test number 839410084281

Result
✓ Passed

Notice O/s/front tyre inner edge worn

Advice Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

966685873244

Result

Notice Advised front discs worn

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	mm.m.m
Current registration	NE NE
Flate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-14
Last registration	2023-06-16
Complete history	See info



Registration #1	2010-10-14	7 mi
Registration #2	2013-10-02	25.224 mi
Registration #3	2014-10-07	32.657 mi
Registration #4	2015-09-25	38.473 mi
Registration #5	2016-10-13	45.527 mi
Registration #6	2017-11-09	53.238 mi
Registration #7	2017-11-13	53.239 mi
Registration #8	2018-03-09	54.650 mi
Registration #9		0.07 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.177 es
Registration #13		11.777 mi
Registration #14		11.177 es
Registration #15		11.777 mi
Registration #16		n

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1380 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/13