



General information

Make	MINI
Model	COOPER S
Colour	Red
Year of manufacture	2015
Top speed	146 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 2



Date	2021-06-27
Pictures	25
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

Entry 1

Date	2021-05-26
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-05
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #10	2023-09-06 10:25
MOT test number	604059656560
Result	✓ Passed
Next expiry date	2024-09-05
Minor	Steering lock not functioning (7.3 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Uneven inner edge (5.2.3 (e))

MOT #9	2023-09-05 13:22
MOT test number	186989038156
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed Cut on worn inner edge (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Uneven inner edge (5.2.3 (e))
Minor	Steering lock not functioning (7.3 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing Slight cracking, also wear at inner edge (5.2.3 (d) (ii))

MOT #8	2022-08-31 11:45
MOT test number	871980304350
Result	✓ Passed

**MOT #7** 2021-09-06 16:00**MOT test number** 559062154944**Result** ✓ Passed**MOT #6** 2021-04-23 15:10**MOT test number** 413524578609**Result** ✓ Passed**MOT #5** 2020-06-19 10:51**MOT test number** 445434248936**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2020-06-19 09:28**MOT test number** 815558267607**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3** 2019-06-18 08:42**MOT test number** 984689982274**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2018-06-27 12:33**MOT test number** 206560067400**Result** ✓ Passed



MOT #1	2018-06-27 07:00
MOT test number	660406706838
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Minor	Nearside Front Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	5 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>SE15RCY</b>
Plate since	2015-05-29
Current registration	<b>SE15RCY</b>
Plate since	2015-05-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-06-30
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2015-06-30	7 mi
Registration #2	2018-06-27	11.208 mi
Registration #3	2018-06-27	11.209 mi
Registration #4	2019-06-18	16.906 mi
Registration #5	2020-06-19	19.871 mi
Registration #6	2020-06-19	19.871 mi
Registration #7	2021-04-23	22.864 mi
Registration #8	2023-09-06	25.277 mi
Registration #9	2023-09-06	25.277 mi
Registration #10	2023-09-06	25.277 mi
Registration #11	2023-09-06	25.277 mi
Registration #12	2023-09-06	25.277 mi
Registration #13	2023-09-06	25.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	F1121009