





report date: 2024-03-29

General information

Make	TOYOTA
Model	AURIS VVT-I TR
Colour	Silver
Year of manufacture	2011
Top speed	175 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.329 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-04	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-18
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #12	20)24-01-15 09:13
MOT test	number	258413646995
Result		✓ Passed
Next expi	iry date	2025-01-18
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing between treads (5.2.3 (d) (ii))		d) (ii))

MOT #11	2023-01-12 12:28
MOT test number	360641014115
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10		2022-01-19 11:48
MOT test	number	184957569213
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing between treads (5.2.3 (d) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.13	1 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing between treads (5	5.2.3 (d) (ii))
Advice	Offside Brake pipe corroded, covered in grease or other material main (1.1.1	1 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
Advice	Offside Front Tyre slightly damaged/cracking or perishing between treads (5.	2.3 (d) (ii))
Advice	Nearside Brake pipe corroded, covered in grease or other material main (1.1.	.11 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing between treads (5.2	2.3 (d) (ii))

MOT #9	2020-12-09 14:15
MOT test number	957572882083
Result	✓ Passed
MOT #8	2020-02-12 10:40
MOT test number	641294949095
Result	✓ Passed
MOT #7	2019-02-11 12:58
MOT test number	812926557492
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MO1 #6	2017-11-13 10:29
MOT test number	689580424019
Result	✓ Passed

MOT #5

MOT test number

527478736359

Result

✓ Passed

MOT #4 2016-11-25 10:02

MOT test number 974537460656

Result × Failed

Advice Nearside Rear Tyre worn close to the legal limit worn uneven on inner (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit worn edges (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit worn uneven on inner (4.1.E.1)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2015-11-26 10:51

MOT test number 497822541354

Result ✓ Passed

 MOT #2
 2014-11-28 16:20

 MOT test number
 867742134389

Result ✓ Passed

MOT #1 2014-11-28 12:19

MOT test number 326972234349

Result X Failed

Fail Nearside Headlamp aim too high (1.8)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim		1.0	i
OWI	ner	nıs	tory

owner mistery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full research	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NE UK
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 9/12



YF61AZR report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-05
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-12-05	18 mi
Registration #2	2014-11-28	23.232 mi
Registration #3	2014-11-28	23.232 mi
Registration #4	2015-11-26	29.502 mi
Registration #5	2016-11-25	37.975 mi
Registration #6	2016-11-26	37.975 mi
Registration #7	2017-11-13	41.139 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 ms

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1515 mm
Length	4245 mm
Wheel base	2600 mm
Kerb weight	1285 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 1

Number of axles 2

Engine number 1NR0399982