



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-07
Pictures	13
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #23	2022-11-11 17:39
MOT test number	710008794101
Result	✓ Passed
Next expiry date	2023-11-11
Advice	Offside Front corner wing damaged slightly
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General under body rust
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
Advice	Brake load sensing valve stiff (1.1.17 (c) (ii))

MOT #22	2021-11-12 14:28
MOT test number	791035631670
Result	✓ Passed
Advice	Gearbox mounting defective

MOT #21	2021-01-04 12:11
MOT test number	249632122696
Result	✓ Passed
Advice	Front and rear exhaust corroded
Advice	Nearside Rear Exhaust mounting defective (6.1.2 (a))
Advice	Gearbox mounting defective
Advice	Rear fuel tank mounting corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2021-01-04 12:11

MOT test number

591783881431

Result**✗ Failed****Advice**

Gearbox mounting defective

Advice

Front and rear exhaust corroded

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification

Nearside Rear Exhaust system insecure rubber bush (6.1.2 (a))

Advice

Rear fuel tank mounting corroded

Advice

Nearside Rear Exhaust mounting defective (6.1.2 (a))

MOT #19

2020-01-03 18:26

MOT test number

252869962771

Result**✓ Passed****Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front and rear exhaust corroded

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Central Rear fuel tank mounting corroded

Advice

Nearside Rear Exhaust mounting defective insecure (6.1.2 (a))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Minor

Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #18**

2019-01-08 14:37

MOT test number

672476608460

Result

✓ Passed

- Advice** Fuel tank straps corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Underside of vehicle has surface corrosion

MOT #17

2019-01-07 13:35

MOT test number

674612019356

Result

✗ Failed

- Advice** Fuel tank straps corroded
- Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Front Brake disc in such a condition that it is seriously weakened (inner face) (1.1.14 (a) (ii))
- Advice** Underside of vehicle has surface corrosion
- Fail** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (outer sill) (6.2.2 (d) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16

2017-06-07 16:49

MOT test number

116720172788

Result

✓ Passed

- Advice** Fuel tank strap corroded
- Advice** Slight blow 1st and 2nd exhaust joint
- Advice** Offside Front lower arm front bush perished
- Advice** Offside Rear Outer sill soft and corroding
- Advice** Front brake discs worn

**MOT #15**

2017-06-05 16:03

MOT test number

470192276107

Result**✗ Failed**

- Advice** Front brake discs worn
- Advice** Fuel tank strap corroded
- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Brake load sensing valve seized (3.6.E.3)
- Advice** Slight blow 1st and 2nd exhaust joint
- Advice** Offside Front lower arm front bush perished
- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)
- Advice** Offside Rear Outer sill soft and corroding
- Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (4.1.D.1a)

MOT #14

2016-01-29 12:48

MOT test number

567829942921

Result**✓ Passed**

- Advice** Nearside Front wing damaged
- Advice** Nearside Front tyre worn low on limit, perished and cut outer sidewall
- Advice** Offside Rear Outer sill holed but not corroded
- Advice** Slight blow 1st and rear exhaust joint
- Advice** Offside Front lower arm front bush perished

**MOT #13**

2016-01-25 17:36

MOT test number

881969431074

Result

✗ Failed

- Fail** Offside Front Driver's seat cannot be secured in the upright position. (6.2.A.2)
- Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp all lights (1.1.A.3f)
- Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)
- Advice** Slight blow 1st and rear exhaust joint
- Advice** Offside Front lower arm front bush perished
- Advice** Offside Rear Outer sill holed but not corroded
- Fail** Nearside Side repeater insecure (1.4.A.2b)
- Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp all lights (1.1.A.3f)
- Advice** Nearside Front wing damaged
- Advice** Nearside Front tyre worn low on limit, perished and cut outer sidewall
- Advice** Offside Rear tyre perished

MOT #12

2014-04-24 12:33

MOT test number

398044714121

Result

✓ Passed

- Notice** Nearside rear wheel slight bind
- Notice** Nearside front tyre perished worn edges
- Notice** Nearside rear tyre worn outer edge
- Notice** Offside rear tyre worn inner edge

MOT #11

2013-04-25 13:26

MOT test number

567385713131

Result

✓ Passed

**MOT #10** 2012-04-26 18:11**MOT test number** 258587812431**Result** ✓ Passed**MOT #9** 2012-04-25 10:39**MOT test number** 598236112140**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar severely distorted (2.4.G.1)**Fail** Offside Front Anti-roll bar missing (2.4.G.1)**MOT #8** 2011-12-08 15:40**MOT test number** 879552741369**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #7** 2010-11-29 15:20**MOT test number** 470893130438**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Suspension joint offside lower dust cover split/missing**MOT #6** 2010-11-29 13:19**MOT test number** 704573830395**Result** ✗ Failed**Notice** Suspension joint nearside lower dust cover split/missing**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Suspension joint offside lower dust cover split/missing

**MOT #5** 2009-11-26 11:28**MOT test number** 331870139346**Result** ✓ Passed

- Notice** Throttle pedal rubber missing
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #4 2009-11-26 11:28**MOT test number** 271950239365**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Notice** Throttle pedal rubber missing
- Pass with rectification** Offside Side repeater not working (1.4.A.2c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Brake load sensing valve linkage seized (3.6.E.3)

MOT #3 2008-12-02 13:43**MOT test number** 660917538364**Result** ✓ Passed**MOT #2** 2007-12-14 09:12**MOT test number** 404108147456**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2006-12-12 10:32
MOT test number	323306046364
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-12-15
Last registration	2022-11-11
Complete history	See info



Registration #1	2003-12-15	18 mi
Registration #2	2006-12-12	16.742 mi
Registration #3	2007-12-14	23.535 mi
Registration #4	2008-12-02	29.441 mi
Registration #5	2009-11-26	36.581 mi
Registration #6	2010-11-29	41.763 mi
Registration #7	2010-11-29	41.763 mi
Registration #8	2011-12-08	47.712 mi
Registration #9	2012-04-25	48.352 mi
Registration #10	2012-04-26	48.352 mi
Registration #11	2013-04-25	54.805 mi
Registration #12	2014-04-24	56.793 mi
Registration #13	2015-05-20	58.787 mi
Registration #14	2016-05-20	60.787 mi
Registration #15	2017-05-20	62.787 mi
Registration #16	2018-05-20	64.787 mi
Registration #17	2019-05-20	66.787 mi
Registration #18	2020-05-20	68.787 mi
Registration #19	2021-05-20	70.787 mi
Registration #20	2022-05-20	72.787 mi
Registration #21	2023-05-20	74.787 mi
Registration #22	2024-05-20	76.787 mi
Registration #23	2025-05-20	78.787 mi
Registration #24	2026-05-20	80.787 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSJ24469875