



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2007
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-07
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	36
Total items failed	7

MOT #20	2024-02-08 15:48
MOT test number	464322563818
Result	✓ Passed
Next expiry date	2025-02-07

MOT #19	2024-02-08 15:48
MOT test number	623449178576
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18	2023-01-25 15:40
MOT test number	390898948365
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2023-01-24 13:43**MOT test number** 335043447580**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2022-02-03 14:19**MOT test number** 386635237836**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**MOT #15** 2021-02-05 11:55**MOT test number** 865488668043**Result** ✓ Passed**MOT #14** 2020-05-06 10:53**MOT test number** 166340500676**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**MOT #13** 2019-04-01 10:21**MOT test number** 890475889330**Result** ✓ Passed**Advice** Rear seat belts not checked

**MOT #12** 2019-03-26 09:18**MOT test number** 834954828306**Result** ✗ Failed**Advice** Rear seat belts not checked**Fail** Offside Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))**MOT #11** 2018-03-16 12:11**MOT test number** 247548592776**Result** ✓ Passed**MOT #10** 2018-03-16 09:16**MOT test number** 800604889966**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2017-03-22 12:28**MOT test number** 311434864134**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Advice** Exhaust deteriorated**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Rear Outer Seat belt anchorage prescribed area is distorted but not considered excessive sill on (5.2.6)**Advice** Offside Rear tyre outer sidewall damaged slightly**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #8**

2017-03-22 09:37

MOT test number

609903305942

Result**✗ Failed**

- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear tyre outer sidewall damaged slightly
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Spanner /service light displayed
- Advice** Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Exhaust deteriorated
- Advice** Nearside Rear Outer Seat belt anchorage prescribed area is distorted but not considered excessive sill on (5.2.6)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)

MOT #7

2016-03-02 09:25

MOT test number

790173522868

Result**✓ Passed**

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front tyre cracking
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2015-03-12 14:59**MOT test number** 178501875428**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #5** 2014-03-12 09:25**MOT test number** 185821174043**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2013-03-18 09:38**MOT test number** 347137073081**Result** ✓ Passed**MOT #3** 2012-03-07 10:47**MOT test number** 417727762096**Result** ✓ Passed**MOT #2** 2011-03-21 15:20**MOT test number** 935990481068**Result** ✓ Passed**MOT #1** 2010-03-26 11:45**MOT test number** 193435480496**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-29
Last registration	2024-02-08
Complete history	See info



Registration #1	2007-03-29	29 mi
Registration #2	2010-03-26	14.594 mi
Registration #3	2011-03-21	19.226 mi
Registration #4	2012-03-07	23.193 mi
Registration #5	2013-03-18	27.244 mi
Registration #6	2014-03-12	31.007 mi
Registration #7	2015-03-12	35.089 mi
Registration #8	2016-03-02	39.153 mi
Registration #9	2017-03-22	43.439 mi
Registration #10	2017-03-22	43.439 mi
Registration #11	2018-03-16	46.056 mi
Registration #12	2019-03-20	50.277 mi
Registration #13	2020-03-20	55.277 mi
Registration #14	2021-03-20	60.277 mi
Registration #15	2022-03-20	65.277 mi
Registration #16	2023-03-20	70.277 mi
Registration #17	2024-03-20	75.277 mi
Registration #18	2025-03-20	80.277 mi
Registration #19	2026-03-20	85.277 mi
Registration #20	2027-03-20	90.277 mi
Registration #21	2028-03-20	95.277 mi
Registration #22	2029-03-20	100.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3180226