





report date: 2024-03-28

#### General information

Make	FIAT
Model	PUNTO EVO ACTIVE
Colour	Black
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

### Entry 1

Date 2022-02-05

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-13
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	28
Total items failed	10

MOT #16	2024-02-14 16:02
MOT test number	127371823811
Result	✓ Passed
Next expiry date	2025-02-13

MOT #15	2024-02-14 15:31
MOT test number	375573646246
Result	<b>X</b> Failed
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #14		2023-01-04 12:02
MOT test	number	849227192211
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Shock absorbers has light misting of oil both (5.3.2 (b))	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #13** 2023-01-04 10:06

MOT test number 290158129405

Result X Failed

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Rear Shock absorbers has light misting of oil both (5.3.2 (b))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Fail** Fuel cap/sealing device missing (6.1.3 (b) (i))

**MOT #12** 2021-08-13 14:21

MOT test number 429536183823

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre in very poor condition (5.2.3 (e))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Items removed from driver's view prior to test

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #11** 2020-08-03 13:16

MOT test number 870876742748

Result \rightarrow Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect Slight leak (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #10** 2019-08-29 09:56 275194096461 **MOT** test number Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Items removed from driver's view prior to test **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

MOT test number

669418578527

Result

Advice Rear silencer corroded.

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

Result

Fail Offside Front Coil spring fractured or broken broken. (5.3.1 (b) (i))

Advice Rear silencer corroded.

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

 MOT #7
 2017-08-26 15:09

 MOT test number
 982217371084

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #6 2017-08-26 15:09 MOT test number 752415787763

Result × Failed

Pass with rectification

Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2016-08-27 12:39

**MOT test number** 277309285410

**Result** ✓ Passed

Advice Rear silencer slightly corroded

MOT #4 2015-08-15 15:20

**MOT test number** 325367325482

Result Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** N/s/f tyre cut on outer sidewall

MOT #3 2014-08-23 10:08

MOT test number 968425034292

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #2 2013-08-21 14:28

MOT test number 897583633297

CarCheck.co.uk page 6/14



report date: 2024-03-28



CarCheck.co.uk page 7/14



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	13 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

SD10UWA

report date: 2024-03-28

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT has Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .	ıve?
*********	
***************************************	
************	
HARMANNA CONTRACTOR OF THE PARTY OF THE PART	
***************************************	
***********	
More inf	<b>o</b> >
Plate changes	
See in this check if this FIAT had different number plates.	

EXECUTE OF THE PROPERTY OF THE

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2024-02-14
Complete history	See info



Registration #1	2010-03-31	19 mi
Registration #2	2013-08-21	18.411 mi
Registration #3	2014-08-23	27.293 mi
Registration #4	2015-08-15	32.356 mi
Registration #5	2016-08-27	40.814 mi
Registration #6	2017-08-26	48.673 mi
Registration #7	2017-08-26	48.673 mi
Registration #8	2018-08-18	54.106 mi
Registration #9	2018-08-22	54.119 mi
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		
Registration #10		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number 5839116