



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT MATCH TDI DSG 105
Colour	Grey
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-23
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-09-28
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #16	2022-09-29 09:46
MOT test number	768325398023
Result	✓ Passed
Next expiry date	2023-09-28

MOT #15	2021-09-27 14:09
MOT test number	203735290403
Result	✓ Passed

MOT #14	2021-05-05 12:19
MOT test number	870352895793
Result	✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-05-19 13:50
MOT test number	774451588766
Result	✓ Passed

**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2020-05-19 08:55**MOT test number** 776390845289**Result** ✗ Failed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2019-04-03 14:40**MOT test number** 184864953794**Result** ✓ Passed**MOT #10** 2018-03-26 12:35**MOT test number** 224240728971**Result** ✓ Passed**MOT #9** 2018-03-26 10:09**MOT test number** 429546639673**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2017-04-11 10:07**MOT test number** 320750058778**Result** ✓ Passed

**MOT #7** 2017-04-11 10:07**MOT test number** 638752684258**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #6** 2016-04-01 11:05**MOT test number** 845678622105**Result** ✓ Passed**MOT #5** 2015-04-02 15:10**MOT test number** 379922895026**Result** ✓ Passed**MOT #4** 2014-04-17 15:24**MOT test number** 468327004167**Result** ✓ Passed**MOT #3** 2013-09-07 15:26**MOT test number** 337630153472**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Emissions to clean too test**Notice** Under-trays fitted obscuring some underside components**Notice** Rear brake pads wearing low**MOT #2** 2012-09-12 15:20**MOT test number** 408796952244**Result** ✓ Passed



MOT #1	2011-08-17 10:34
MOT test number	337769321470
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-15
Last registration	2022-09-29
Complete history	<a href="#">See info</a>



Registration #1	2008-09-15	7 mi
Registration #2	2011-08-17	41.299 mi
Registration #3	2012-09-12	58.251 mi
Registration #4	2013-09-07	59.925 mi
Registration #5	2014-04-17	61.700 mi
Registration #6	2015-04-02	69.769 mi
Registration #7	2016-04-01	76.061 mi
Registration #8	2017-04-11	84.030 mi
Registration #9	2017-04-11	84.030 mi
Registration #10	2018-04-11	91.999 mi
Registration #11	2019-04-11	99.968 mi
Registration #12	2020-04-11	107.937 mi
Registration #13	2021-04-11	115.906 mi
Registration #14	2022-04-11	123.875 mi
Registration #15	2023-04-11	131.844 mi
Registration #16	2024-04-11	139.813 mi
Registration #17	2025-04-11	147.782 mi
Registration #18	2026-04-11	155.751 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Max. allowed weight	1920 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	BXE 676824