





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH M 1000 X BLUEHDI
Colour	Black
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	54.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-06-24

Pictures 36

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-21
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #8	2023-07-21 09:17
MOT test number	961468399573
Result	✓ Passed
Next expiry date	2024-07-21
Minor Offside Front Windscreen wiper blade defective smearing (3.4 (b) (i))	
Advice Front Lower Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple I (4.7.1 (b) (i))	amps or light sources

MOT #7	2023-07-21 09:17
MOT test number	567337061356
Result	× Failed
Minor Offside Front Windscreen wiper blade defective smearing (3.4 (b) (i))	
Advice Front Lower Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #6	2022-07-22 08:55
MOT test number	757981948556
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2021-07-22 15:28

MOT test number 814653432475

MOT #4 2020-12-30 11:36

MOT test number 726952538971

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #3 2020-12-30 11:36

MOT test number 111850374235

Result X Failed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #2 2019-12-30 15:48

MOT test number 453840599410

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number
734679467085

Result

Minor
Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification
Offside Headlamp insecure (4.1.1 (c))

Minor
Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification
Contacted (6.1.4 (a) (i))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full research		OEN

THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-01-06
Last registration	2023-07-21
Complete history	See info



Registration #1	2017-01-06	26 mi
Registration #2	2019-12-30	33.872 mi
Registration #3	2019-12-30	33.872 mi
Registration #4	2020-12-30	42.422 mi
Registration #5	2020-12-30	42.422 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.77 es
-		11.777 ea 11.777 ea
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



Dimensions &	weig	ht
--------------	------	----

Width	2204 mm
Height	1895 mm
Length	4959 mm
Kerb weight	1522 kg
Max. allowed weight	2640 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHJ0004342

CarCheck.co.uk page 12/12