




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI ALTITUDE
Colour	Black
Year of manufacture	2007
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg
CO2 emission	278 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-10-23
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-25
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	32
Total items failed	10

MOT #18	2023-10-30 15:55
---------	------------------

MOT test number	911134241202
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-29
------------------	------------

Advice	Engine and under bonnet trays fitted
Advice	Play in steering rack inner joint(s) both
Advice	Both front tyres worn on the inner edges - keep in check
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front brake pads getting low - keep in check
Advice	Items removed from driver's view prior to test
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Brake disc worn, but not excessively lip on nearside disc has been ground off (1.1.14 (a) (i))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #17**

2023-10-26 10:08

MOT test number

604599157631

Result**✗ Failed**

- Advice** Play in steering rack inner joint(s) both
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Engine and under bonnet trays fitted
- Advice** Rear Brake disc worn, but not excessively lip on nearside disc has been ground off (1.1.14 (a) (i))
- Advice** Both front tyres worn on the inner edges - keep in check
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Side repeater light intensity significantly reduced (4.4.3 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front brake pads getting low - keep in check

MOT #16

2022-10-28 09:22

MOT test number

468510675431

Result**✓ Passed**

**MOT #15** 2021-10-26 15:09**MOT test number** 975028335329**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**MOT #14** 2021-10-26 07:54**MOT test number** 466428094533**Result** ✗ Failed**Fail** Horn not working (7.7 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Front Nail in tyre**MOT #13** 2021-02-19 16:21**MOT test number** 754216995660**Result** ✓ Passed**MOT #12** 2021-02-19 16:21**MOT test number** 369949460002**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2019-02-11 12:16**MOT test number** 927905772246**Result** ✓ Passed

**MOT #10** 2018-02-09 15:59**MOT test number** 635842512592**Result** ✓ Passed**MOT #9** 2017-02-07 13:12**MOT test number** 977485013684**Result** ✓ Passed**MOT #8** 2017-02-07 13:11**MOT test number** 175711954060**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #7** 2016-02-12 13:54**MOT test number** 233856613092**Result** ✓ Passed**MOT #6** 2016-02-12 13:30**MOT test number** 319706322687**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #5** 2015-02-06 10:06**MOT test number** 175177435437**Result** ✓ Passed**Notice** Both front tyres worn on inner edges - recommend wheel alignment checked and new tyres fitted.

**MOT #4** 2014-02-07 16:52**MOT test number** 186858134051**Result** ✓ Passed**MOT #3** 2014-01-23 16:50**MOT test number** 396613624017**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**Notice** Eml light on dash**MOT #2** 2013-02-12 11:43**MOT test number** 627933943053**Result** ✓ Passed**MOT #1** 2011-05-23 11:27**MOT test number** 646573841150**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-12-03
Last registration	2023-10-30
Complete history	See info



Registration #1	2007-12-03	25 mi
Registration #2	2011-05-23	39.463 mi
Registration #3	2013-02-12	54.549 mi
Registration #4	2014-01-23	61.786 mi
Registration #5	2014-02-07	61.824 mi
Registration #6	2015-02-06	69.306 mi
Registration #7	2016-02-12	76.600 mi
Registration #8	2016-02-12	76.600 mi
Registration #9	2017-02-07	83.663 mi
Registration #10	2017-02-07	83.663 mi
Registration #11	2018-02-09	89.091 mi
Registration #12	2019-02-09	95.519 mi
Registration #13	2020-02-09	101.947 mi
Registration #14	2021-02-09	108.375 mi
Registration #15	2022-02-09	114.803 mi
Registration #16	2023-02-09	121.231 mi
Registration #17	2023-10-30	127.659 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKS 056903