





General information

CRDI STRIKE
r
)
mph
seconds
eed Manual

Engine & fuel consumption

Power	108 BHP
Engine capacity	1.493 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С





Internet history	
Entry 1	
Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	9
Total items failed	9

MOT #17	2024-03-13 10:18
MOT test number	769913376081
Result	✓ Passed
Next expiry date	2025-03-13

MOT #16	2023-03-14 11:49
MOT test number	761756158882
Result	✓ Passed
Advice Rear tyres 175/70/14 front tyres 165/70/14	

MOT #15	2022-03-09 11:17
MOT test number	682590875378
Result	✓ Passed

MOT #14	2021-03-11 12:57
MOT test number	111476740959
Result	✓ Passed

MOT #13	2020-02-18 14:04
MOT test number	130162190137
Result	✓ Passed





MOT #12	2019-02-20 17:44
MOT test number	381624131821
Result	✓ Passed
MOT #11	2019-02-20 14:00
MOT test number	292169528518
Result	🗙 Failed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #10	2018-03-06 09:33
MOT test number	547387137139
Result	✓ Passed

MOT #9	2018-03-05 11:36
MOT test number	872796455003
Result	🗙 Failed
Fail Front Windscreen has damage to an area in excess of a 10mm circle withinFail Front Windscreen washer provides insufficient washer liquid (8.2.3)	zone 'A' (8.3.1a)

МОТ #8	2017-03-01 15:21
MOT test number	937694562616
Result	✓ Passed



Μ	K1	00	C	R	G
1	report o	date:	202	24-0	3-28

MOT #7	2017-02-27 10:22
MOT test number	906458951537
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front position lamp(s) not working sidelight (1.1.A.3b)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Rear wiper blade split	

MOT #6	2016-02-26 16:38
MOT test number	496642365542
Result	✓ Passed
Advice Nearside rear tyre wearing low	

MOT #5	2016-02-26 10:18
MOT test number	266098704699
Result	🗙 Failed
Advice Nearside rear tyre wearing low	
Fail Rear Registration plate lamp not working both (1.1.C.1d)	

МОТ #4	2015-02-03 10:27
MOT test number	866564835036
Result	✓ Passed
Notice Nearside front tyre wearing low	

МОТ #3	2014-02-25 09:54
MOT test number	125246754024
Result	✓ Passed





MOT #2	2013-02-15 10:12
MOT test number	547566543090
Result	✓ Passed
Notice Anti thieft full cap fitted unable too check correct seal	
MOT #1	2013-02-15 10:12
MOT test number	678686843017
Result	🗙 Failed
Pass with rectification Offside Front Headlamp aim too high (1.8)	



Tax & MOT check

Tax due: 1 May 2024	√ Taxed	Expires: 13 March 2025	✓ МОТ
Tax status			Valid until 1 May
Days left			2
MOT expiry date			13 March 2025
Full MOT history			See MOT history
Tax calculation			
		40	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damaye 2	e e et al
Date	 1.
Category	 AMP
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



MK100RG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-01
Last registration	2024-03-13
Complete history	<u>See info</u>



Registration #1	2010-03-01	25 mi
Registration #2	2013-02-15	20.862 mi
Registration #3	2014-02-25	25.576 mi
Registration #4	2015-02-03	31.562 mi
Registration #5	2016-02-26	38.027 mi
Registration #6	2016-02-26	38.027 mi
Registration #7	2017-02-27	45.547 mi
Registration #8	2017-03-01	45.559 mi
Registration #9	2018-03-05	53.055 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1650 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13