



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVT-I XT-R
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	10.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-07-31
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-07
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	33
Total items failed	4

MOT #22	2023-08-02 13:12
MOT test number	604797446740
Result	✓ Passed
Next expiry date	2024-08-07
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

MOT #21	2023-08-02 09:06
MOT test number	892151501419
Result	✗ Failed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
MAJOR	Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #20** 2022-07-22 08:38**MOT test number** 990218282779**Result** ✓ Passed**MOT #19** 2021-07-30 09:53**MOT test number** 351631900158**Result** ✓ Passed**MOT #18** 2020-08-06 13:40**MOT test number** 981068027661**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear exhaust deteriorated**MOT #17** 2020-08-06 10:56**MOT test number** 986168793148**Result** ✗ Failed**Advice** Rear exhaust deteriorated**MAJOR** Front Registration plate insecure (0.1 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2019-08-08 09:32**MOT test number** 417833086987**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2018-07-03 14:31**MOT test number** 989240692405**Result** ✓ Passed**MOT #14** 2017-07-04 16:10**MOT test number** 259137212062**Result** ✓ Passed**Advice** Rear Side walls are cracked**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #13** 2017-07-04 13:37**MOT test number** 702010559146**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Front Brake pad(s) less than 1.5 mm thick Both sides (3.5.1g)**Advice** Rear Side walls are cracked**MOT #12** 2016-07-01 09:55**MOT test number** 973115195500**Result** ✓ Passed

**MOT #11** 2015-07-10 17:31**MOT test number** 885831495108**Result** ✓ Passed**MOT #10** 2014-06-19 12:19**MOT test number** 247340174448**Result** ✓ Passed**MOT #9** 2014-05-30 13:27**MOT test number** 118280054128**Result** ✓ Passed**MOT #8** 2014-05-30 09:38**MOT test number** 626500554197**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-12-17 13:48**MOT test number** 817911753314**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust corroded**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2012-12-18 10:34**MOT test number** 137363052361**Result** ✓ Passed

**MOT #5** 2011-12-16 09:50**MOT test number** 859720951347**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-12-16 10:51**MOT test number** 193690050344**Result** ✓ Passed**MOT #3** 2010-12-16 10:51**MOT test number** 804770250384**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2009-12-16 09:47**MOT test number** 221170959381**Result** ✓ Passed**MOT #1** 2008-12-17 14:33**MOT test number** 222532758330**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
7 August 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	7 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>FG05LXA</b>
Plate since	2019-09-28
Current registration	<b>FG05LXA</b>
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-04-22
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2005-04-22	16 mi
Registration #2	2008-12-17	33.047 mi
Registration #3	2009-12-16	34.616 mi
Registration #4	2010-12-16	35.703 mi
Registration #5	2011-12-16	37.641 mi
Registration #6	2012-12-18	39.421 mi
Registration #7	2013-12-17	41.973 mi
Registration #8	2014-05-30	43.499 mi
Registration #9	2014-05-30	43.499 mi
Registration #10	2014-06-19	43.766 mi
Registration #11	2015-07-10	49.370 mi
Registration #12	2016-07-01	53.285 mi
Registration #13	2016-07-01	53.285 mi
Registration #14	2016-07-01	53.285 mi
Registration #15	2016-07-01	53.285 mi
Registration #16	2016-07-01	53.285 mi
Registration #17	2016-07-01	53.285 mi
Registration #18	2016-07-01	53.285 mi
Registration #19	2016-07-01	53.285 mi
Registration #20	2016-07-01	53.285 mi
Registration #21	2016-07-01	53.285 mi
Registration #22	2016-07-01	53.285 mi
Registration #23	2016-07-01	53.285 mi
Registration #24	2016-07-01	53.285 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1705 mm
Length	4265 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1AZ1828286