



LG64RVR


report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Blue
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	E







## Internet history

### Entry 3

Date	2021-10-12
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk


### Entry 2

Date	2021-10-12
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk

### Entry 1

Date	2021-10-11
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #9	2023-08-25 14:09
MOT test number	576064286387
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Offside Rear tyre stones in tread
Advice	Tpms warning on
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #8	2022-09-07 08:54
MOT test number	886220452827
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Items removed from driver's view prior to test
Advice	Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #7** 2022-09-07 08:35**MOT test number** 925190816845**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Items removed from driver's view prior to test**MOT #6** 2021-09-07 15:32**MOT test number** 771027630423**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**MOT #5** 2020-09-25 09:30**MOT test number** 818400981625**Result** ✓ Passed**MOT #4** 2019-09-25 14:53**MOT test number** 279499736501**Result** ✓ Passed**MOT #3** 2018-10-12 13:18**MOT test number** 554046148304**Result** ✓ Passed



MOT #2	2017-10-04 14:14
MOT test number	597546628387
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit CI235/40W18 95W XL SPC5 (4.1.E.1)

MOT #1	2017-10-04 11:38
MOT test number	117464125449
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit CI235/40W18 95W XL SPC5 (4.1.E.1)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively special order blades (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
6 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	6 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LG64RVR</b>
Plate since	2019-09-29
Current registration	 <b>LG64RVR</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-29
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2014-09-29	16 mi
Registration #2	2017-10-04	17.372 mi
Registration #3	2017-10-04	17.372 mi
Registration #4	2018-10-12	23.012 mi
Registration #5	2019-09-25	26.615 mi
Registration #6	2020-09-25	30.449 mi
Registration #7	2021-09-07	33.426 mi
Registration #8	2022-09-25	35.277 mi
Registration #9	2023-08-25	35.277 mi
Registration #10	2023-08-25	35.277 mi
Registration #11	2023-08-25	35.277 mi
Registration #12	2023-08-25	35.277 mi
Registration #13	2023-08-25	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBK81075