





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | IX20 STYLE |
| Colour | Blue |
| Year of manufacture | 2014 |
| Top speed | 104 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 137 Nm at 5.000 rpm |
| Engine capacity | 1.396 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 140 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-31

Pictures 3

Listing price <u>View report</u>







source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-05-05 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 12 |
| Total items failed | 6 |

| MOT #12 | 2024-04-26 13:33 |
|--|------------------|
| MOT test number | 992137242078 |
| Result | ✓ Passed |
| Next expiry date | 2025-05-05 |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |

| MOT #11 | 2024-04-26 08:11 |
|--|------------------|
| MOT test number | 365048406594 |
| Result | X Failed |
| Fail Offside Parking brake inoperative on one side (1.4.1 (a)) | |
| Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) | |
| Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) | |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |

| MOT #10 | | 2023-04-12 11:06 |
|----------|--|------------------|
| MOT test | number | 545721964081 |
| Result | | ✓ Passed |
| Advice | Offside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/12



MOT #9 2022-04-28 15:02

MOT test number 743569680378

MOT #8 2022-04-28 09:24

MOT test number 542326094159

Result ★ Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Tyre pressure warning lamp illuminated

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7 2021-05-06 08:16

MOT test number 169923720649

Result ✓ Passed

MOT #6 2021-05-05 10:44

MOT test number 962015868654

Result ★ Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively SPLIT (3.4 (b) (ii))

MOT #5 2020-07-21 16:19

MOT test number 526430346890

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #4 2020-07-21 11:16

MOT test number 890587024809

Result X Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Offside Front Windscreen wiper blade defective loose (3.4 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-05-25 12:07

MOT test number 504058081878

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2018-05-26 16:08

MOT test number 425983751655

Advice Front Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MOT #1 2017-05-24 14:55

MOT test number 836864807860

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 5 May 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r | | 4 I |
|---|--|------------|
| | | |
| | | |
| | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| *************************************** | | |
| | More info > | |
| Plate changes | | |
| See in this check if this HYUNDAI had different number plates. | | |
| Number of plates | | |
| Current registration | OK ON THE STATE OF | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-05-30 |
| Last registration | 2024-04-26 |
| Complete history | See info |



| Registration #1 | 2014-05-30 | 27 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-05-24 | 12.665 mi |
| Registration #3 | 2018-05-26 | 16.054 mi |
| Registration #4 | 2019-05-25 | 19.965 mi |
| Registration #5 | 2020-07-21 | 25.997 mi |
| Registration #6 | 2020-07-21 | 25.998 mi |
| Registration #7 | | 71.777 66 |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 71.777 66 |
| Registration #12 | | D.777 es |
| Registration #13 | | 11.777 es |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1600 mm |
| Length | 4100 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1268 kg |
| Max. allowed weight | 1710 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |