



F J110HB


report date: 2024-03-28

General information

Make	FORD
Model	FIESTA
Colour	Black
Year of manufacture	2011
Gearbox	-

Engine & fuel consumption

Engine capacity	1.242 cc
Fuel type	Petrol
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-12-11
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-03-14
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	17
Total items failed	18

MOT #14 2023-03-15 11:28

MOT test number 964763323672

Result ✓ Passed

Next expiry date 2024-03-14

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** General under body corrosion
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2021-10-18 14:36

MOT test number 669501995363

Result ✓ Passed

MOT #12 2020-11-06 14:59

MOT test number 264344467547

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2020-11-03 09:10

MOT test number

755581587928

Result**✗ Failed**

Fail Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting hole in sill (6.2.2 (d) (i))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Bonnet wont open cannot check key components

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (l))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Minor Nearside Front Tyre obviously under inflated (5.2.3 (l))

Fail Offside Front Service brake excessively binding (1.2.1 (f))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Offside Rear Tyre obviously under inflated (5.2.3 (l))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-09-09 09:50

MOT test number

841160062477

Result**✓ Passed****MOT #9**

2018-09-12 09:00

MOT test number

779528840673

Result**✓ Passed**

**MOT #8** 2018-03-20 09:58**MOT test number** 115699262661**Result** ✓ Passed**Advice** Offside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #7** 2018-03-12 16:26**MOT test number** 310191335011**Result** ✗ Failed**Advice** Offside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**Fail** Offside Rear Upper Axle beam has excessive vertical movement between stub axle and axle beam axle beam (2.5.A.1a)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Upper Axle beam has excessive vertical movement between stub axle and axle beam axle bush (2.5.A.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2017-02-15 09:54**MOT test number** 766719187815**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-02-13 15:05**MOT test number** 886426715861**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**MOT #4** 2016-03-01 15:55**MOT test number** 975646334078**Result** ✓ Passed**MOT #3** 2016-02-29 14:09**MOT test number** 176095606354**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #2** 2015-03-04 14:26**MOT test number** 636793965073**Result** ✓ Passed**MOT #1** 2014-03-05 10:48**MOT test number** 239324664010**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✗
MOT

Expired:
14 March 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	14 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-03-28
Current registration	XXXXXX
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-04
Last registration	2023-03-15
Complete history	See info



Registration #1	2011-03-04	7 mi
Registration #2	2014-03-05	22.292 mi
Registration #3	2015-03-04	34.348 mi
Registration #4	2016-02-29	45.362 mi
Registration #5	2016-03-01	45.369 mi
Registration #6	2017-02-13	55.996 mi
Registration #7	2017-02-15	55.999 mi
Registration #8	2018-03-12	67.389 mi
Registration #9	2019-03-01	78.777 mi
Registration #10	2019-03-01	78.777 mi
Registration #11	2019-03-01	78.777 mi
Registration #12	2019-03-01	78.777 mi
Registration #13	2019-03-01	78.777 mi
Registration #14	2019-03-01	78.777 mi
Registration #15	2019-03-01	78.777 mi
Registration #16	2019-03-01	78.777 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 5

Engine number BL52429