



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2004
Top speed	143 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	218 g/km
CO2 label	K






Internet history

Entry 2

Date	2021-06-28
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-26
Pictures	31
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-21
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	29
Total items failed	6

MOT #21	2023-07-06 10:51
MOT test number	568374284090
Result	✓ Passed
Next expiry date	2024-07-21

MOT #20	2022-07-04 14:18
MOT test number	682626844095
Result	✓ Passed

MOT #19	2022-07-04 10:57
MOT test number	200542970344
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #18	2021-06-30 14:41
MOT test number	610418548003
Result	✓ Passed

**MOT #17** 2021-06-28 11:43**MOT test number** 862106859171**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #16** 2020-07-03 10:59**MOT test number** 770696226063**Result** ✓ Passed**Advice** Outer sill covers fitted to the vehicle**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine covers and under trays fitted to the vehicle**MOT #15** 2020-07-03 08:43**MOT test number** 624639782030**Result** ✗ Failed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Outer sill covers fitted to the vehicle**Fail** Nearside Rear Direction indicator incorrect colour back up lamp (4.4.3 (a))**Advice** Engine covers and under trays fitted to the vehicle**MOT #14** 2019-07-16 12:45**MOT test number** 691793183955**Result** ✓ Passed

**MOT #13** 2018-07-02 15:02**MOT test number** 437794543668**Result** ✓ Passed**MOT #12** 2017-07-11 14:10**MOT test number** 783500517042**Result** ✓ Passed**MOT #11** 2016-07-15 12:47**MOT test number** 678157024318**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #10** 2015-07-15 16:30**MOT test number** 655216995136**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9**

2014-07-22 08:37

MOT test number

539333004275

Result

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Oil leak
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #8

2013-07-16 12:23

MOT test number

206627593424

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** O/s/f tyre slightly out of shape
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Oil leak
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #7

2012-07-19 10:44

MOT test number

238481402295

Result

✓ Passed



MOT #6	2011-07-20 10:50
--------	------------------

MOT test number	969741401221
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2010-07-14 11:58
--------	------------------

MOT test number	600605990106
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2009-07-15 10:48
--------	------------------

MOT test number	880156699103
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #3	2008-07-16 10:53
--------	------------------

MOT test number	581058098118
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2008-07-16 10:53
--------	------------------

MOT test number	733968798143
-----------------	--------------

Result	✗ Failed
--------	----------

Pass with rectification	Nearside Front Headlamp aim too low (1.8)
--------------------------------	---

MOT #1	2007-07-10 09:46
--------	------------------

MOT test number	213021997169
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	FT04TYY
Plate since	2024-03-28
Current registration	FT04TYY
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-07-20
Last registration	2023-07-06
Complete history	See info



Registration #1	2004-07-20	7 mi
Registration #2	2007-07-10	13.227 mi
Registration #3	2008-07-16	18.036 mi
Registration #4	2009-07-15	22.992 mi
Registration #5	2010-07-14	27.654 mi
Registration #6	2011-07-20	32.395 mi
Registration #7	2012-07-19	36.796 mi
Registration #8	2013-07-16	41.065 mi
Registration #9	2014-07-22	43.208 mi
Registration #10	2015-07-15	45.282 mi
Registration #11	2016-07-15	47.481 mi
Registration #12	2017-07-11	50.377 mi
Registration #13	2018-07-11	50.377 mi
Registration #14	2019-07-11	50.377 mi
Registration #15	2020-07-11	50.377 mi
Registration #16	2021-07-11	50.377 mi
Registration #17	2022-07-11	50.377 mi
Registration #18	2023-07-11	50.377 mi
Registration #19	2024-07-11	50.377 mi
Registration #20	2025-07-11	50.377 mi
Registration #21	2026-07-11	50.377 mi
Registration #22	2027-07-11	50.377 mi
Registration #23	2028-07-11	50.377 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430530152