



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 RAPIER HDI (90BHP)
Colour	Red
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E







Internet history

Entry 3



Date	2022-08-11
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2


Date	2021-09-09
Pictures	18
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-08
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-20
MOT pass rate	60 %
MOT passed	18
Failed MOT tests	12
Total advice items	13
Total items failed	38

MOT #30	2023-08-16 07:51
MOT test number	288998460884
Result	✓ Passed
Next expiry date	2024-08-20
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Rear Exhaust mounting defective Bracket rusty (6.1.2 (a))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Front Coil spring corroded Both sides (5.3.1 (b) (i))
Advice	Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))

**MOT #29**

2023-08-16 07:51

MOT test number

183381731715

Result**✗ Failed**

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Exhaust mounting defective Bracket rusty (6.1.2 (a))
- Pass with rectification** Offside Front Side repeater incorrect colour (4.4.3 (a))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (ii))
- Pass with rectification** Nearside Front Side repeater incorrect colour (4.4.3 (a))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #28

2022-08-02 06:55

MOT test number

126781317435

Result**✓ Passed**

- Advice** Offside Rear Stub axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))
- Minor** Central Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #27

2021-08-10 15:26

MOT test number

587817201483

Result**✓ Passed**

- Advice** Offside Rear Stub axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))

**MOT #26** 2021-08-09 15:41**MOT test number** 128990070239**Result** ✗ Failed**Fail** Offside Windscreen washer not working (3.5 (a))**Fail** Nearside Windscreen washer not working (3.5 (a))**MOT #25** 2020-08-11 09:06**MOT test number** 108643782920**Result** ✓ Passed**MOT #24** 2020-08-11 09:06**MOT test number** 295936370547**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #23** 2019-08-13 13:40**MOT test number** 476377971485**Result** ✓ Passed**MOT #22** 2019-08-12 14:16**MOT test number** 409777573955**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Horn not working (7.7 (a) (ii))**Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced condensed (4.1.4 (b))

**MOT #21** 2018-08-01 10:20**MOT test number** 728348149190**Result** ✓ Passed**MOT #20** 2018-08-01 10:02**MOT test number** 799846622618**Result** ✗ Failed

- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Rear Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm edge (5.2.3 (e))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm edge (5.2.3 (e))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a))

MOT #19 2017-08-04 09:23**MOT test number** 888656899010**Result** ✓ Passed**MOT #18** 2017-08-03 08:36**MOT test number** 149288164104**Result** ✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Body insecure and dangerous to other road users engine undertray (6.1.B.1b)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #17** 2016-08-15 11:44**MOT test number** 988853618912**Result** ✓ Passed**MOT #16** 2016-08-15 08:28**MOT test number** 186984091356**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #15** 2015-08-04 09:25**MOT test number** 761860037413**Result** ✓ Passed**MOT #14** 2015-08-04 09:25**MOT test number** 738407308350**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #13** 2014-08-11 10:12**MOT test number** 347543724287**Result** ✓ Passed**MOT #12** 2013-08-15 10:12**MOT test number** 317797723206**Result** ✓ Passed

**MOT #11** 2013-08-15 10:12**MOT test number** 236947323218**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2012-08-09 09:57**MOT test number** 445682022263**Result** ✓ Passed**MOT #9** 2011-08-18 16:14**MOT test number** 259300831241**Result** ✓ Passed**MOT #8** 2011-08-18 09:17**MOT test number** 867310931257**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #7** 2010-08-18 08:35**MOT test number** 993190730267**Result** ✓ Passed**MOT #6** 2010-08-18 08:35**MOT test number** 494230930295**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2009-07-27 15:06**MOT test number** 354378509415**Result** ✓ Passed**MOT #4** 2009-07-27 11:15**MOT test number** 164578609253**Result** ✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear coil spring incomplete (2.4.C.1a)
- Fail** Rear Exhaust has part of the system excessively deteriorated (7.1.1a)

MOT #3 2008-08-13 10:31**MOT test number** 430846128277**Result** ✓ Passed**MOT #2** 2007-08-21 08:48**MOT test number** 104533937256**Result** ✓ Passed**MOT #1** 2006-08-01 09:18**MOT test number** 390113316438**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	2003-10-11
Last registration	2023-08-16
Complete history	See info



Registration #1	2003-10-11	10 mi
Registration #2	2006-08-01	18.297 mi
Registration #3	2007-08-21	36.006 mi
Registration #4	2008-08-13	43.181 mi
Registration #5	2009-07-27	46.570 mi
Registration #6	2009-07-27	46.576 mi
Registration #7	2010-08-18	48.263 mi
Registration #8	2011-08-18	50.953 mi
Registration #9	2011-08-18	50.959 mi
Registration #10	2012-08-09	52.307 mi
Registration #11	2013-08-15	54.237 mi
Registration #12	2014-08-11	56.837 mi
Registration #13	2015-08-04	60.520 mi
Registration #14	2015-08-04	60.520 mi
Registration #15	2016-08-15	63.681 mi
Registration #16	2016-08-15	63.681 mi
Registration #17	2016-08-15	63.681 mi
Registration #18	2016-08-15	63.681 mi
Registration #19	2016-08-15	63.681 mi
Registration #20	2016-08-15	63.681 mi
Registration #21	2016-08-15	63.681 mi
Registration #22	2016-08-15	63.681 mi
Registration #23	2016-08-15	63.681 mi
Registration #24	2016-08-15	63.681 mi
Registration #25	2016-08-15	63.681 mi
Registration #26	2016-08-15	63.681 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	DYLH3149927