



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Silver
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	161 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-16
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-23
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	28
Total items failed	5

MOT #19	2023-05-02 14:09
MOT test number	164566329972
Result	✓ Passed
Next expiry date	2024-05-23
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #18	2023-04-26 10:30
MOT test number	546692156695
Result	✗ Failed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #17	2022-05-17 16:22
MOT test number	737356235601
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2022-05-10 13:57

MOT test number

417364797370

Result**✗ Failed**

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2021-05-24 10:37

MOT test number

576996138682

Result**✓ Passed**

Advice Parking brake lever has little reserve travel

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2020-09-09 12:44

MOT test number

900557405609

Result**✓ Passed**

Advice Parking brake has little reserve travel

MOT #13

2020-09-09 10:19

MOT test number

486295317520

Result**✗ Failed**

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Parking brake has little reserve travel

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2019-09-05 16:27**MOT test number** 104893928804**Result** ✓ Passed

- Advice** Nearside Rear tyre has uneven wear on inner edge
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))
- Advice** Parking brake lever has little reserve travel
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))

MOT #11 2018-09-15 15:48**MOT test number** 676145008526**Result** ✓ Passed

- Advice** Both rear tyres wearing unevenly on inner edges
- Advice** Parking brake has little reserve travel

MOT #10 2017-08-14 13:17**MOT test number** 834902039271**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear tyres starting to wear unevenly on inner edges
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #9 2016-09-08 13:57**MOT test number** 739262865800**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Inner tyre has splits no cords exposed

**MOT #8** 2015-04-23 11:21**MOT test number** 677033915155**Result** ✓ Passed**MOT #7** 2014-11-25 12:35**MOT test number** 556289624319**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #6** 2013-11-28 11:08**MOT test number** 408812833474**Result** ✓ Passed**Notice** Offside front tyre wearing low on tread inner edge**MOT #5** 2012-11-28 09:58**MOT test number** 958003032398**Result** ✓ Passed**MOT #4** 2011-12-16 12:29**MOT test number** 418440551424**Result** ✓ Passed**MOT #3** 2011-12-15 12:12**MOT test number** 108579541383**Result** ✗ Failed**Notice** Nearside rear tyre has deep cut in outer wall but not to cord**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Nail in offside front tyre



MOT #2	2010-11-24 12:35
MOT test number	851418520329
Result	✓ Passed
MOT #1	2009-11-27 15:27
MOT test number	613481439379
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 KR56XEW
Plate since	2019-06-29
Current registration	 KR56XEW
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-11-27
Last registration	2023-05-02
Complete history	See info



Registration #1	2006-11-27	7 mi
Registration #2	2009-11-27	18.778 mi
Registration #3	2010-11-24	22.783 mi
Registration #4	2011-12-15	27.450 mi
Registration #5	2011-12-16	27.450 mi
Registration #6	2012-11-28	31.942 mi
Registration #7	2013-11-28	37.292 mi
Registration #8	2014-11-25	42.848 mi
Registration #9	2015-04-23	44.542 mi
Registration #10	2016-09-08	49.019 mi
Registration #11	2017-08-14	55.170 mi
Registration #12	2018-05-29	55.170 mi
Registration #13	2019-05-29	55.170 mi
Registration #14	2020-05-29	55.170 mi
Registration #15	2021-05-29	55.170 mi
Registration #16	2022-05-29	55.170 mi
Registration #17	2023-05-02	55.170 mi
Registration #18	2023-05-02	55.170 mi
Registration #19	2023-05-02	55.170 mi
Registration #20	2023-05-02	55.170 mi
Registration #21	2023-05-02	55.170 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030203754