





report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2013
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/15




Internet history

Entry 1

Date 2021-10-22

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-23
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	49
Total items failed	7

MOT #12	2023-06-16 12:14
MOT test number	481047187826
Result	✓ Passed
Next expiry date	2024-06-23

MOT #11	2023-06-16 09:53
MOT test number	611485119129
Result	X Failed
Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))	
Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))	

MOT #10	2022-06-24 08:53
MOT test number	562359341723
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in errear bush (5.3.4 (a) (i))	excessive movement
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in exrear bush (5.3.4 (a) (i))	cessive movement
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/15



MOT #9 2021-11-11 16:09

MOT test number 243987275298

✓ Passed Result **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/15



MOT #8 2021-10-29 15:44

MOT test number 246621384392

Result **X** Failed **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i)) **Advice** Offside Front Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Brake pipe excessively corroded front to rear (1.1.11 (c)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 5/15



MOT #7 2021-06-30 10:05

MOT test number 213600026312

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

MOT #6 2021-06-30 10:05

MOT test number 334523560636

Result X Failed

Pass with rectification Horn not working (7.7 (a) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

CarCheck.co.uk page 6/15



MOT #5 2020-07-01 12:03

MOT test number 423737139506

Result ✓ Passed

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

MOT #4 2019-03-26 10:59

MOT test number 830300282327

Advice Nearside Front Nail in tyre

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #3 2018-03-13 10:41

MOT test number 864153595208

Result
✓ Passed

Advice Nearside Front coil spring corroded (2.4.C.1b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 7/15



MOT #2	2017-02-07 10:57
MOT test number	959628883495
Result	✓ Passed
MOT #1	2016-01-26 13:05
MOT #1 MOT test number	2016-01-26 13:05 381118576848

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner	history
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this NISSAN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-31
Last registration	2023-06-16
Complete history	See info



Registration #1	2013-01-31	20 mi
Registration #2	2016-01-26	26.076 mi
Registration #3	2017-02-07	31.834 mi
Registration #4	2018-03-13	37.481 mi
Registration #5	2019-03-26	43.713 mi
Registration #6	2020-07-01	50.356 mi
Registration #7	2021-06-30	57.320 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 14/15



Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	153324

CarCheck.co.uk page 15/15