





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S 90
Colour	Black
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	210 Nm at 1.800 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-08-11

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-26
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	6

MOT #16	2024-02-27 17:01
MOT test number	342728175717
Result	✓ Passed
Next expiry date	2025-02-26
Advice Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))	

MOT #15	2022-10-22 16:03
MOT test number	182758438868
Result	✓ Passed

MOT #14		2021-10-14 15:50
MOT test	number	970081848711
Result		✓ Passed
Advice	Plastic cover fitted top of the engine and under the floor	
Advice Vehicle structure is corroded but structural rigidity is not significantly reduced under the floor few places (6.1.1 (c) (i))		

CarCheck.co.uk page 3/13



MOT #13

Advice

SL09J0J report date: 2024-03-28

2020-09-28 14:32

MOT test number

Result

Minor Front Windscreen wiper blade defective both side (3.4 (b) (i))

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Minor Front Outer Drive shaft joint constant velocity boot severely deteriorated both side (6.1.7 (g) (i))

Advice Engine and under covers fitted obscuring some components

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both side rear ones (5.3.4 (a) (i))

 MOT #12
 2019-03-26 11:21

 MOT test number
 716870228829

 Result
 ✓ Passed

Advice Front Brake pad(s) wearing thin n/s and o/s (1.1.13 (a) (ii))

Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2018-04-03 10:29
MOT test number 151271692295

MOT #10 2018-04-03 10:29

MOT test number 283134729575

Result X Failed

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

CarCheck.co.uk page 4/13



MOT #9 2017-03-21 10:31

MOT test number 916233703619

Result ✓ Passed

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #8 2017-03-21 10:31

MOT test number 529294834736

Result X Failed

Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

Advice Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

Pass with rectification Offside Front coil spring broken (2.4.C.1a)

MOT #7 2016-03-17 12:11

MOT test number 708056269029

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Lower Suspension arm has slight play in a track control arm inner bush front

(2.5.B.2b)

MOT #6 2015-03-18 11:15

MOT test number 429127375071

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



 MOT #5
 2014-03-25 10:28

 MOT test number
 277084784010

Result Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2014-03-25 10:28

MOT test number 687184784018

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #3 2013-04-02 11:13

MOT test number 688342493052

Result Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2013-04-02 11:13

MOT test number 369112993029

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

MOT #1 2012-03-27 10:20

MOT test number 737477582002

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 10/13



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-28
Last registration	2024-02-27
Complete history	See info



Registration #1	2009-03-28	19 mi
Registration #2	2012-03-27	26.713 mi
Registration #3	2013-04-02	34.942 mi
Registration #4	2014-03-25	42.025 mi
Registration #5	2015-03-18	49.087 mi
Registration #6	2016-03-17	55.625 mi
Registration #7	2017-03-21	62.304 mi
Registration #8	2017-03-21	62.304 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		0.074
Registration #16		71.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Max. allowed weight	2210 kg

Additional information

-	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

CarCheck.co.uk page 13/13

Number of axles	2
Engine number	BXF 030202