





report date: 2024-03-28

General information

Make	HYUNDAI
Model	KONA PREMIUM
Colour	Grey
Year of manufacture	2019
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

_		•		_	-
-	n	т	rv	,	

Life y 1	
Date	2022-05-21
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-18
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	8
Total items failed	6

MOT #6	2024-03-19 08:34
MOT test number	588549047815
Result	✓ Passed
Next expiry date	2025-03-18
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

 MOT #5
 2024-03-15 16:21

 MOT test number
 703147997999

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4	2023-03-17 14:10
MOT test number	168211188787
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Rear Exhaust has a major leak of exhaust gases box joint (6.1.2 (a))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #2

MOT test number

637397453906

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #1 2022-02-21 13:21 781019735883 **MOT** test number × Failed Result **Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



BG19EYO report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




BG19EYO
report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
See in this check if this frondal had different humber plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



BG19EYO report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-03-01
Last registration	2024-03-19
Complete history	See info



Registration #1	2019-03-01	27 mi
Registration #2	2022-02-21	36.978 mi
Registration #3	2022-02-22	36.980 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



BG19EYO report date: 2024-03-28

Car features


The HYUNDAI factory car options list is only available in the premium report.		
S0225	Air conditioning	
S0295		
S0482		
S0501		
S0566		
S0567		
S0569		

View the complete HYUNDAI factory list for this vehicle $\underline{\text{here}}.$

More info >

Safety ratings

NCAP rating	****
Adult	87%
Children	85%
Pedestrian	62%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1565 mm
Length	4165 mm
Wheel base	2600 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	50 I	
Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2	page 11/11