



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





MOT history

MOT expiry date	2024-10-16
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	12

MOT #17	2023-10-12 08:34
MOT test number	402681387087
Result	✓ Passed
Next expiry date	2024-10-16

MOT #16	2022-10-17 16:32
MOT test number	864472210547
Result	✓ Passed
Advice	Rear Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #15	2021-10-12 14:01
MOT test number	932479101389
Result	✓ Passed
Advice	Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14** 2021-10-08 13:26**MOT test number** 324754813542**Result** ✗ Failed**Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 235-40-18 (5.2.3 (d) (i))**MOT #13** 2020-09-16 08:48**MOT test number** 863971623573**Result** ✓ Passed**MOT #12** 2019-10-09 15:09**MOT test number** 848579467529**Result** ✓ Passed**MOT #11** 2019-10-05 09:18**MOT test number** 321596477048**Result** ✗ Failed**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall ;235/40/18 (5.2.3 (d) (i))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-10-09 13:37**MOT test number** 732303800703**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Coil spring corroded All four (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-10-08 11:15**MOT test number** 162028930612**Result** ✗ Failed**Fail** Offside Rear Outer Brake pad(s) incorrectly mounted (1.1.13 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Brake performance not tested (1.2.1 (g))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Side repeater obviously incorrectly positioned (4.4.3 (a))**Advice** Coil spring corroded All four (5.3.1 (b) (i))**MOT #8** 2017-10-09 15:15**MOT test number** 500123272646**Result** ✓ Passed**MOT #7** 2017-10-09 08:35**MOT test number** 403904793195**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Central Front Exhaust system not adequately supported bracket broken (7.1.1)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #6** 2016-10-21 08:58**MOT test number** 424330202956**Result** ✓ Passed

**MOT #5** 2015-10-07 08:38**MOT test number** 446590922333**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #4** 2014-10-22 11:27**MOT test number** 847605494263**Result** ✓ Passed**Notice** Nsf tyre has several cuts no chords or ply showing**MOT #3** 2013-10-16 10:56**MOT test number** 175699683246**Result** ✓ Passed**MOT #2** 2012-10-12 10:26**MOT test number** 595076082246**Result** ✓ Passed**MOT #1** 2012-10-12 10:26**MOT test number** 715026782237**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WF59UPR
Plate since	2019-03-28
Current registration	WF59UPR
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-26
Last registration	2023-10-12
Complete history	See info



Registration #1	2009-10-26	12 mi
Registration #2	2012-10-12	22.504 mi
Registration #3	2013-10-16	32.089 mi
Registration #4	2014-10-22	41.729 mi
Registration #5	2015-10-07	51.129 mi
Registration #6	2016-10-21	59.772 mi
Registration #7	2017-10-09	67.779 mi
Registration #8	2017-10-09	67.781 mi
Registration #9	2018-10-08	75.368 mi
Registration #10	2019-10-08	83.368 mi
Registration #11	2020-10-08	91.368 mi
Registration #12	2021-10-08	99.368 mi
Registration #13	2022-10-08	107.368 mi
Registration #14	2023-10-08	115.368 mi
Registration #15	2024-03-28	123.368 mi
Registration #16	2024-03-28	131.368 mi
Registration #17	2024-03-28	139.368 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8C35715