



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2025-04-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	33
Total items failed	9

MOT #16	2024-04-23 15:04
MOT test number	363628659749
Result	✓ Passed
Next expiry date	2025-04-25
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear beam axle corroded but not weekend

MOT #15	2024-04-23 08:25
MOT test number	948637440429
Result	✗ Failed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear beam axle corroded but not weekend
Fail	Tyre has a tear, caused by separation or partial failure of its structure all four tyres (5.2.3 (d) (ii))

MOT #14	2023-04-24 08:05
MOT test number	482362548392
Result	✓ Passed
Advice	Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii))

**MOT #13**

2022-04-26 13:06

MOT test number

789835514053

Result

✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Tyre slightly damaged/cracking or perishing all four cracked also from 2014 (5.2.3 (d) (ii))

MOT #12

2022-04-26 07:51

MOT test number

556922557406

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Tyre slightly damaged/cracking or perishing all four cracked also from 2014 (5.2.3 (d) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #11

2021-03-12 14:48

MOT test number

563609459375

Result

✓ Passed

Advice Tyre slightly damaged/cracking or perishing all 4 tyres starting to perish and crack (5.2.3 (d) (ii))

Advice Nearside Rear silencer outer skin corroded

**MOT #10**

2021-03-11 11:05

MOT test number

851951473023

Result**✗ Failed****Advice** Tyre slightly damaged/cracking or perishing all 4 tyres starting to perish and crack (5.2.3 (d) (ii))**Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))**Advice** Nearside Rear silencer outer skin corroded**Advice** Offside Rear tail light unit damaged**Fail** Service brake excessively binding rear brakes (1.2.1 (f))**MOT #9**

2020-01-07 15:08

MOT test number

946795484387

Result**✓ Passed****Advice** Rear exhaust corroded**MOT #8**

2019-01-15 16:23

MOT test number

690295207589

Result**✓ Passed****Advice** Front Exhaust mounting defective (6.1.2 (a))**MOT #7**

2019-01-15 15:24

MOT test number

910799554575

Result**✗ Failed****Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (h) (i))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6** 2018-01-09 15:58**MOT test number** 195622124699**Result** ✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Rear exhaust outer casing separated/ corroded
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

MOT #5 2017-01-17 13:22**MOT test number** 266394931942**Result** ✓ Passed

- Advice** Rear exhaust box corroded
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #4 2016-01-12 12:38**MOT test number** 278174061095**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear exhaust section outer casing seperated
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2015-01-06 15:16
MOT test number	989506405055
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2014-01-13 14:33
MOT test number	195693114403
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2013-01-14 12:40
MOT test number	189014313075
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-23
Last registration	2024-04-23
Complete history	See info



Registration #1	2010-01-23	28 mi
Registration #2	2013-01-14	17.774 mi
Registration #3	2014-01-13	23.843 mi
Registration #4	2015-01-06	29.306 mi
Registration #5	2016-01-12	35.244 mi
Registration #6	2017-01-17	41.162 mi
Registration #7	2018-01-09	43.567 mi
Registration #8	2019-01-15	45.061 mi
Registration #9	2019-01-15	45.061 mi
Registration #10	2020-01-15	45.061 mi
Registration #11	2021-01-15	45.061 mi
Registration #12	2022-01-15	45.061 mi
Registration #13	2023-01-15	45.061 mi
Registration #14	2024-01-15	45.061 mi
Registration #15	2025-01-15	45.061 mi
Registration #16	2026-01-15	45.061 mi
Registration #17	2027-01-15	45.061 mi
Registration #18	2028-01-15	45.061 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203