





report date: 2024-03-29

General information

Make	KIA
Model	RIO GS
Colour	Silver
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-08


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2024-10-31
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #11	2023-10-24 12:01
MOT test number	361699728526
Result	✓ Passed
Next expiry date	2024-10-31

MOT #10	2022-11-01 12:13
MOT test number	243318338207
Result	✓ Passed

MOT #9		2021-09-21 14:30
MOT test	number	923478660197
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Advice

ULZ6321report date: 2024-03-29

MOT test number

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2020-09-16 11:10
MOT test number	439995393187
Result	✓ Passed
MOT #6	2019-08-30 14:32
MOT test number	212997964953
Result	✓ Passed
MOT #5	2018-09-14 15:39
MOT test number	238492714639
Result	√ Passed
MOT #4	2017-09-07 10:55
MOT test number	887205416311
Result	✓ Passed
Advice Both rear brake discs corroded on inner faces	

Front Sub-frame corroded but not seriously weakened (2.4.G.1)

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Offside Rear tyre has light cracking in tread area

Advice Exhaust flanges corroded

Advice Rear wiper blade deteriorated

MOT #2	2015-09-10 13:31
MOT test number	611095299947
Result	✓ Passed
Advice Rear wiper blade split	

MOT #1	2014-09-20 13:36
MOT test number	425453564277
Result	✓ Passed

CarCheck.co.uk page 5/12



ULZ6321

report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



ULZ6321

report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
manage of the same	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NIE.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-09-20
Last registration	2023-10-24
Complete history	See info



Registration #1	2007-09-20	9 mi
Registration #2	2014-09-20	35.516 mi
Registration #3	2015-09-10	37.195 mi
Registration #4	2016-09-03	39.845 mi
Registration #5	2017-09-07	43.901 mi
Registration #6	2018-09-14	50.343 mi
Registration #7	2019-08-30	60.570 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1079 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1.	2/12

Number of axles 2

Engine number G4EE7H11294