



report date: 2024-03-28

General information

Make	FORD
Model	FIESTA EDGE
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D





## MOT history

MOT expiry date	2024-10-31
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	25
Total items failed	19

MOT #16	2023-11-01 13:13
MOT test number	791115306223
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-11-01 13:13
MOT test number	682831189668
Result	✗ Failed
Pass with rectification	Stop lamp(s) not working n/s + o/s (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Direction indicator incorrect colour n/s + o/s (4.4.3 (a))

MOT #14	2022-03-02 17:05
MOT test number	224069424388
Result	✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2022-03-01 19:46

**MOT test number**

524129487453

**Result****✗ Failed****Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Rear Tyre tread depth below requirements of 1.6mm n/s + o/s (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12**

2020-09-24 14:39

**MOT test number**

700516949807

**Result****✓ Passed****Advice** Tyre worn close to legal limit/worn on edge all four tyres low on tread (5.2.3 (e))**MOT #11**

2020-09-24 10:48

**MOT test number**

965577619340

**Result****✗ Failed****Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge all four tyres low on tread (5.2.3 (e))**MOT #10**

2019-09-12 14:18

**MOT test number**

288629364178

**Result****✓ Passed****Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front door damage

**MOT #9** 2019-09-12 09:26**MOT test number** 392803336274**Result** ✗ Failed**Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front door damage**Advice** Nearside Non obligatory mirror damaged**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #8** 2018-09-20 09:54**MOT test number** 673769556109**Result** ✓ Passed**Advice** Surpentine belt breaking up**Advice** Coolant leak**MOT #7** 2017-08-02 14:58**MOT test number** 989950745295**Result** ✓ Passed

**MOT #6** 2017-08-01 10:03**MOT test number** 918947853347**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Side repeater missing (1.4.A.2b)
- Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**MOT #5** 2016-08-02 14:40**MOT test number** 413141555388**Result** ✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2016-08-01 08:35

**MOT test number**

555625893037

**Result****✗ Failed****Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Indicator switch faulty (1.4.A.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Front brake fluctuating, but not excessively both (3.7.B.3)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2015-08-04 09:59

**MOT test number**

149156515232

**Result****✓ Passed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2**

2014-08-04 12:11

**MOT test number**

428576914282

**Result****✓ Passed****Notice** Both front tyres worn on inner edge



MOT #1	2013-09-09 16:00
MOT test number	758872253207
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-13
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2010-12-13	15 mi
Registration #2	2013-09-09	44.212 mi
Registration #3	2014-08-04	57.871 mi
Registration #4	2015-08-04	67.614 mi
Registration #5	2016-08-01	77.762 mi
Registration #6	2016-08-02	77.765 mi
Registration #7	2017-08-01	87.805 mi
Registration #8	2017-08-02	87.805 mi
Registration #9	2018-09-20	90.560 mi
Registration #10	2019-09-20	95.377 mi
Registration #11	2019-09-20	95.377 mi
Registration #12	2019-09-20	95.377 mi
Registration #13	2019-09-20	95.377 mi
Registration #14	2019-09-20	95.377 mi
Registration #15	2019-09-20	95.377 mi
Registration #16	2019-09-20	95.377 mi
Registration #17	2019-09-20	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	AU64848